2000 MOTOR MAGAZINE INDEX

HOW TO USE THIS INDEX

General subjects are listed first, with a month and page reference (if applicable), followed by related subjects and their references. The reference gives the month of the magazine in which a topic appeared, followed by a period and the page or pages. For example, under the general subject of "Environmental Protection Agency (EPA)," the subtopic "contact information" was covered in the January issue on page 45, and is indexed as "Jan.45."

Regarding numbers (for example, years, model numbers, engine sizes, etc.), they are arranged in increasing order, without regard to alphabetization. Thus, years are listed with the earliest year first. Likewise, BMW "3-series" would appear before BMW "5-series," and Audi "A4" would be listed before Audi "A6."

A

3-series (BMW), air bag light on (1994-99), Jun.68
4Runner (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
buzzing evap canister (1996), Nov.75
cylinder head service (1988-95), Apr.65
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
snow in HVAC box (1996-98), May.76
steering gear service precaution (1996 newer), Dec.50
surging idle (1988-94), Jan.20, 22
upgraded automatic transmission (1996), May.72
5-series (BMW), air bag light on (1997-99), Jun.68
7-series (BMW), air bag light on (1995-99), Jun.68
24-7 (Ford), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76
88 Royale (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
90 (Audi), MIL on, various EGR DTCs (1995), Sep.75
98 Regency (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
300 Hemi C (Chrysler), concept vehicle unveiled at 2000 North American International Auto Show, Mar.75-76
300M (Chrysler)
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
318 (BMW), 1.8-liter, jolt on acceleration (1994-95), Mar.86
323is (BMW)
2.5-liter, valve timing mechanism jams (1998-99), Apr.57
2.8-liter, valve timing mechanism jams (1998-99), Apr.57
328i (BMW)
2.5-liter, valve timing mechanism jams (1996-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1996-98), Apr.57
328is (BMW)
2.5-liter, valve timing mechanism jams (1996-99), Apr.57
2.8-liter, valve timing mechanism jams (1996-99), Apr.57
525i (BMW), air bag light on (1995-99), Jun.68
528i (BMW)
2.5-liter, valve timing mechanism jams (1997-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1997-98), Apr.57
530i (BMW), air bag light on (1995-99), Jun.68
540i (BMW)
4.4-liter, cranks but won't start (1997-99), May.74-75
air bag light on (1995-99), Jun.68
626 (Mazda)
dead power driver's seat (1993-94), Jan.63
MIL on with DTCs P0300 through P0306 (1997), Sep.70
740i (BMW)
4-liter, inoperative oil level sensor (1995), Sep.73
4.4-liter, cranks but won't start (1997-99), May.74-75
740iL (BMW), 4-liter, inoperative oil level sensor (1995), Sep.73
750i (BMW), 4.4-liter, cranks but won't start (1997-99), May.74-75
850 (Volvo)
fuel pulsation damper (1997 newer), Sep.76
new O2 sensor wiring (1996-98), Apr.60
new PCMs (1996-97), Oct.26
new starter motor (after 1997), Jan.61
900 (Saab)
battery drain (1987-89), Jan.63
brake vibration (1994 on), Jun.64
engine compartment noise (1994 newer), May.76
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
911 (Porsche), intake camshaft service (1999 on), May.73
911 Carrera (Porsche)
front end creaking/groaning (1995), Jun.64
vacuum line caution (1995-96), Apr.65
911 Carrera 2 (Porsche), fuel odor (prior to 1994), Jan.63
911 Carrera 4 (Porsche)
fuel odor (prior to 1994), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
911 Carrera Cabriolet (Porsche), convertible top motor service (1996), Dec.56
911 Turbo (Porsche)
front end creaking/groaning (1996), Jun.64
fuel odor (1991-94), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
vacuum line caution (1996), Apr.65
960 (Volvo), spring sound from steering wheel (1992-94), Feb.71
2000 Ford/AAA Student Auto Skills, national finals winners, Aug.55
2000 Light Truck Service Report, Jan.32-33, 36-42
2000 North American International Auto Show, report, Mar.75-81
2001 Domestic New Vehicle Warranties wall chart, Nov.26
2001 Domestic Tech Preview
Aurora (Oldsmobile), Nov.27
Aztek (Pontiac), Nov.24-25
Corvette (Chevrolet), Nov.25-26
Escape (Ford), Nov.32
General Motors
stability control, Nov.27
vans reworked for handicapped, Nov.28
Minivans (Chrysler), Nov.28, 30
PT Cruiser (Plymouth), Nov.28
Saturn, Nov.26-27
Sebring (Chrysler), Nov.30, 32
Stratus (Dodge), Nov.30, 32
2001 Import Tech Roundup
adaptive cruise control, Dec.24-26
Allroad Quattro (Audi), Dec.32
C-Class (Mercedes-Benz), Dec.32
Civic (Honda), Dec.29-30
CL (Acura), Dec.30-32
I30 (Infiniti), Dec.34
IS 300 (Lexus), Dec.28
LS 430 (Lexus), Dec.26, 28
Maxima (Nissan), Dec.34
MDX (Acura), Dec.30-32
MR-2 (Toyota), Dec.28-29
Outback Wagon H-6 (Subaru), Dec.34
RAV4 (Toyota), Dec.28-29
S-Class (Mercedes-Benz), Dec.32
Tribute (Mazda), Dec.33
V70 Cross Country (Volvo), Dec.33-34
2001 Imported New Vehicle Warranties wall chart, Dec.35-37
2500 (Dodge), accelerated front brake wear (1994-97), Jan.62
2500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
3000GT (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
3500 (Dodge), accelerated front brake wear (1994-97), Jan.62
3500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
6000 (Pontiac), misfire with a/c or heater on (1987), Aug.12-13
9000 (Saab)
engine compartment noise (1994 newer), May.76
speedometer quits working (1996-98), Dec.56
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
wrong grounding point locations (1993 newer), Apr.64
A Glimpse at Fuel Cell Vehicles, Dec.44-46
A Show of Hands

2000 MOTOR MAGAZINE INDEX

HOW TO USE THIS INDEX

General subjects are listed first, with a month and page reference (if applicable), followed by related subjects and their references. The reference gives the month of the magazine in which a topic appeared, followed by a period and the page or pages. For example, under the general subject of "Environmental Protection Agency (EPA)," the subtopic "contact information" was covered in the January issue on page 45, and is indexed as "Jan.45."

Regarding numbers (for example, years, model numbers, engine sizes, etc.), they are arranged in increasing order, without regard to alphabetization. Thus, years are listed with the earliest year first. Likewise, BMW "3-series" would appear before BMW "5-series," and Audi "A4" would be listed before Audi "A6."

A

3-series (BMW), air bag light on (1994-99), Jun.68
4Runner (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
buzzing evap canister (1996), Nov.75
cylinder head service (1988-95), Apr.65
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
snow in HVAC box (1996-98), May.76
steering gear service precaution (1996 newer), Dec.50
surging idle (1988-94), Jan.20, 22
upgraded automatic transmission (1996), May.72
5-series (BMW), air bag light on (1997-99), Jun.68
7-series (BMW), air bag light on (1995-99), Jun.68
24-7 (Ford), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76
88 Royale (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
90 (Audi), MIL on, various EGR DTCs (1995), Sep.75
98 Regency (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
300 Hemi C (Chrysler), concept vehicle unveiled at 2000 North American International Auto Show, Mar.75-76
300M (Chrysler)
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
318 (BMW), 1.8-liter, jolt on acceleration (1994-95), Mar.86
323is (BMW)
2.5-liter, valve timing mechanism jams (1998-99), Apr.57
2.8-liter, valve timing mechanism jams (1998-99), Apr.57
328i (BMW)
2.5-liter, valve timing mechanism jams (1996-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1996-98), Apr.57
328is (BMW)
2.5-liter, valve timing mechanism jams (1996-99), Apr.57
2.8-liter, valve timing mechanism jams (1996-99), Apr.57
525i (BMW), air bag light on (1995-99), Jun.68
528i (BMW)
2.5-liter, valve timing mechanism jams (1997-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1997-98), Apr.57
530i (BMW), air bag light on (1995-99), Jun.68
540i (BMW)
4.4-liter, cranks but won't start (1997-99), May.74-75
air bag light on (1995-99), Jun.68
626 (Mazda)
dead power driver's seat (1993-94), Jan.63
MIL on with DTCs P0300 through P0306 (1997), Sep.70
740i (BMW)
4-liter, inoperative oil level sensor (1995), Sep.73
4.4-liter, cranks but won't start (1997-99), May.74-75
740iL (BMW), 4-liter, inoperative oil level sensor (1995), Sep.73
750i (BMW), 4.4-liter, cranks but won't start (1997-99), May.74-75
850 (Volvo)
fuel pulsation damper (1997 newer), Sep.76
new O2 sensor wiring (1996-98), Apr.60
new PCMs (1996-97), Oct.26
new starter motor (after 1997), Jan.61
900 (Saab)
battery drain (1987-89), Jan.63
brake vibration (1994 on), Jun.64
engine compartment noise (1994 newer), May.76
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
911 (Porsche), intake camshaft service (1999 on), May.73
911 Carrera (Porsche)
front end creaking/groaning (1995), Jun.64
vacuum line caution (1995-96), Apr.65
911 Carrera 2 (Porsche), fuel odor (prior to 1994), Jan.63
911 Carrera 4 (Porsche)
fuel odor (prior to 1994), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
911 Carrera Cabriolet (Porsche), convertible top motor service (1996), Dec.56
911 Turbo (Porsche)
front end creaking/groaning (1996), Jun.64
fuel odor (1991-94), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
vacuum line caution (1996), Apr.65
960 (Volvo), spring sound from steering wheel (1992-94), Feb.71
2000 Ford/AAA Student Auto Skills, national finals winners, Aug.55
2000 Light Truck Service Report, Jan.32-33, 36-42
2000 North American International Auto Show, report, Mar.75-81
2001 Domestic New Vehicle Warranties wall chart, Nov.26
2001 Domestic Tech Preview
Aurora (Oldsmobile), Nov.27
Aztek (Pontiac), Nov.24-25
Corvette (Chevrolet), Nov.25-26
Escape (Ford), Nov.32
General Motors
stability control, Nov.27
vans reworked for handicapped, Nov.28
Minivans (Chrysler), Nov.28, 30
PT Cruiser (Plymouth), Nov.28
Saturn, Nov.26-27
Sebring (Chrysler), Nov.30, 32
Stratus (Dodge), Nov.30, 32
2001 Import Tech Roundup
adaptive cruise control, Dec.24-26
Allroad Quattro (Audi), Dec.32
C-Class (Mercedes-Benz), Dec.32
Civic (Honda), Dec.29-30
CL (Acura), Dec.30-32
I30 (Infiniti), Dec.34
IS 300 (Lexus), Dec.28
LS 430 (Lexus), Dec.26, 28
Maxima (Nissan), Dec.34
MDX (Acura), Dec.30-32
MR-2 (Toyota), Dec.28-29
Outback Wagon H-6 (Subaru), Dec.34
RAV4 (Toyota), Dec.28-29
S-Class (Mercedes-Benz), Dec.32
Tribute (Mazda), Dec.33
V70 Cross Country (Volvo), Dec.33-34
2001 Imported New Vehicle Warranties wall chart, Dec.35-37
2500 (Dodge), accelerated front brake wear (1994-97), Jan.62
2500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
3000GT (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
3500 (Dodge), accelerated front brake wear (1994-97), Jan.62
3500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
6000 (Pontiac), misfire with a/c or heater on (1987), Aug.12-13
9000 (Saab)
engine compartment noise (1994 newer), May.76
speedometer quits working (1996-98), Dec.56
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
wrong grounding point locations (1993 newer), Apr.64
A Glimpse at Fuel Cell Vehicles, Dec.44-46
A Show of Hands

receives 10th International Automotive Media Conference (IAMC) Gold Medallion award, Dec.62
using hand cleaners correctly, Jul.28-30, 32-34, 36
A4 (Audi)
2.8-liter, engine cranks but won't start (1998-99), Dec.57
delayed 1-2 shift after cold start (1996 newer), Jun.61
low fuel level warning (1995), Mar.86-87
MIL on, low fuel level (1995), Apr.58
A6 (Audi)
2.8-liter, engine cranks but won't start (1998-99), Dec.57
delayed 1-2 shift after cold start (1995 newer), Jun.61
low fuel level warning (1995), Mar.86-87
MIL on, low fuel level (1995), Apr.58
A8 (Audi), delayed 1-2 shift after cold start (1997 newer), Jun.61
AAIA see Automotive Aftermarket Industry Association (AAIA)
AAIW see Automotive Aftermarket Industry Week (AAIW)
AAPEX see Automotive Aftermarket Products Expo (AAPEX)
ABS see Antilock brake systems (ABS)
A/C systems
see also Cooling systems; HVAC systems; Refrigerants
Altima (Nissan), a/c switch stuck on (1993-97), Apr.28
Kent-Moore, ACR 2000 A/C Service Center, Apr.28, 30
Maxima (Nissan), a/c switch sticks on or off (1996-98), Apr.28
Mobile Air Conditioning Society (MACS), 2000 A/C Report, Apr.22-26, 28, 30
Accent (Hyundai)
revised TCMs (1996), Nov.75-76
timing chain noise (1997), Jun.68
Acclaim (Plymouth)
3-liter, harsh shifting (1992-95), Feb.69
intermittent cruise control (1989-95), Oct.28
PCM reflashing tips (1995), Dec.50
Accord (Honda)
2.2-liter
clogged EGR passages (1990 newer), May.14, 16
finding the fast-idle valve (1995), Jul.14-15
revised EGR system (1994-97), Jul.14
timing belt/water pump replacement precaution, Dec.6, 8
brake light stays on (1998), Apr.63
cracking rubber in harmonic balancer (1990-93), Aug.14, 17
engine and dash warning lights fail when ignition key released (1990-93), Jul.14
steering rack squeak (1990-93), Mar.87
Achieva (Oldsmobile)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
Acura, Honda/OnStar/XM Satellite Radio team up to offer mobile communication services, Jul.62-63
Addresses see under Contact information
Aerostar (Ford)
blower motor squeak/chirp (1992-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-97), Feb.72
popping/clunking when braking and turning (1991-93), Jul.66
transmission DTCs stored in memory (1997), May.76
whistling/hissing from transmission (1997), Aug.59
Aftermarket see Automotive aftermarket industry
Airbags, HVAC diagnosing and servicing precaution, Apr.38
Airsept, Service Compressor Suction Screen Kit, Aug.66, Sep.30
Airtex Products
Fall/Winter Bounty Program, Oct.30
fuel pumps pass NASCAR quality standards, Jan.64
website address, Jan.64
AJ16 (Jaguar), waterlogged PCM (1995), May.77
ALI see Automotive Lift Institute (ALI)
Alignment see Wheel alignment
All Pro/Bumper to Bumper
joins Automotive Service Association (ASA), Feb.73
You Drop the Flag promotion, Jun.75
Allante (Cadillac), oil ring installation revision (1993), Aug.61
ALLDATA
2000 database, Jun.75
strategic alliance with MechanicNet.com, Jul.61
Alliance of State Automotive Aftermarket Associations (ASAAA), Global Automotive Aftermarket Symposium (GAAS), Jun.2
AlliedSignal, two new brake catalogs, Feb.73
Allroad Quattro (Audi), 2001 Import Tech Roundup, Dec.32
Alternators, new designs, May.22, 24-25
Altima (Nissan)
a/c switch stuck on (1993-97), Apr.28
diagnosing oil leaks (1993-98), Sep.16, 20-21
MIL on with DTC P0300 (1997-1/2), Jul.72
MIL on with DTCs P0130 and/or P0136 (1997), Sep.70
American Lung Association, protest dropping Florida emissions tests, Jul.63, 65
American Remanufacturers
CV axle components catalog, Aug.62
remanufactured brake component catalog, May.79
AMI see Automotive Management Institute (AMI)
Amigo (Isuzu), 3.2-liter, updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
Amsoil
Spring, 2000 product catalog, Jun.75
synthetic ATF+4 transmission fluid, Jul.75
Antilock brake systems (ABS)
see also Brake systems
diagnostics with current probe and scope, Jun.27-28, 30-31
isolating lockup problems, Mar.6-7
sensors/on-board computer software add greater safety features to new vehicles, Sep.22, 24
system operation, Jun.27
traction control system (TCS) explained, Sep.24
APRA see Automotive Parts Rebuilders Association (APRA)
ARA Services, ARAccelerator PARTSonline recycler-to-recycler parts locator website, Jun.75
Aremco Products, Pyro-Putty 2400 high temperature stainless steel paste, Oct.36
Around the World in 80 Days Motor Challenge, Aug.55-56
ASA see Automotive Service Association (ASA)
ASA Image-Network
fighting negative image of automotive aftermarket industry, Aug.46
website address, Aug.47
ASAAA see Alliance of State Automotive Aftermarket Associations (ASAAA)
ASE see National Institute for Automotive Service Excellence (ASE)
Association for Career and Technical Education, Automotive Awards of Excellence winners, Feb.73
Astro (Chevrolet)
ABS light on/spongy pedal (1994), Nov.4, 6
climate control knobs spin (1996-97), Jul.73
ATP, Re-Seal seal rejuvenator, Apr.68
Audi
see also specific models
heated mirror mysteries (1997 on), Jun.70
Aurora (Oldsmobile)
2001 Domestic Tech Preview, Nov.27
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter, updated fuel pressure readings (1998), May.72
brake noise (1997-98), Jul.68
oil ring installation revision (1997), Aug.61
Auto Meter, BVA-200 hand held tester, Oct.36
Auto Value Associates, Advanced Counterpoint Training Series, May.79
AUTOdealerjobs.com, new automotive careers website, Feb.73
Automatic transmission systems
see also Transmission systems
diagnostics with infrared thermometers, Mar.25
OE Scheduled Maintenance Handbook Tech Tips, fluid & filters, Feb.36
Automotive aftermarket industry
fighting negative image of automotive aftermarket industry, Jun.40-43, Aug.46
Global Automotive Aftermarket Symposium (GAAS), Jun.2
trends for the new year, Dec.4
unfair competition, Jan.2, 4
wins OBDII information battle, Nov.68
Automotive Aftermarket Industry Association (AAIA)
Aftermarket Factbook, Sep.66
association directory, Aug.62
Automotive Aftermarket Industry Week (AAIW), Sep.77
contact information, Sep.66
Global Automotive Aftermarket Symposium (GAAS), Jun.2
survey participants needed, Jun.75
Automotive Aftermarket Industry Week (AAIW), website address, Sep.77
Automotive Aftermarket Products Expo (AAPEX), Sep.77
Automotive Electronics Services
DMM training video, Nov.81
Wire-Tap sharp wire piercer, Mar.91
Automotive Engine Rebuilders Association (AERA), online marketplace, Sep.77
Automotive Leadership Institute, AMI certified shop management training courses, Sep.77
Automotive Lift Institute (ALI)
ANSI/ALI ALOIM-2000 safety requirements, Nov.80
contact information, Jul.74, Nov.80
member company directory, Sep.77
Vehicle Lifting Points for Frame Engaging Lifts, Jul.74
website address, Sep.77
Automotive Management Institute (AMI)
contact information, Oct.30
Excel 2000 resource development program, Apr.66
management seminars, Oct.30
Automotive Parts Rebuilders Association (APRA)
CV & Racks Clinic, Apr.66
e-commerce website, Jan.64
Global Automotive Aftermarket Symposium (GAAS), Jun.2
Volume Transmission Clinic, Apr.66
Automotive Service Association (ASA)
2000 annual meeting, Jun.53-54
Arizona affiliate rejoins, Jan.56
partners with Department of Environmental Quality (DEQ), Feb.63
partners with GreatMechanics.com, Apr.66
protest dropping Florida emissions tests, Jul.63, 65
shop licensing report, Jul.62
Automotive Service Association of Oregon, pursues shop licensing, Sep.64
Automotive Service Training, Silver Bullets Diagnostics Tips Manual, Sep.27
Automotive Solutions, LeakFind 12 volt leak detection system, Apr.68
Automotive Video, Inc., Five Days of Thunder training seminar, Oct.30
Automotive Warehouse Distributors Association (AWDA), Global Automotive Aftermarket Symposium (GAAS), Jun.2
Autovia
connecting repair shops with suppliers via the Internet, Jun.54, 56
new manufacturer catalogs added to online database, Oct.31
Avalon (Toyota), steering gear service precaution (1996 newer), Dec.50
Avenger (Dodge)
2-liter, new transmission software (1996-97), Apr.59-60
2.5-liter, head gasket running change (1995-2000), Jun.66
intermittent cruise control (1995-99), Oct.28
PCM reflashing tips (1995-99), Dec.50
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
AVM, StrongArm 2000 Application & Buyer's Guide, May.79
AWDA see Automotive Warehouse Distributors Association (AWDA)
Aztek (Pontiac), 2001 Domestic Tech Preview, Nov.24-25

B

B-3000 (Mazda), coolant and/or refrigerant leak (1998), Dec.48
B-series (Mazda)
ABS light on, with DTC 5 (1997), Aug.59
rattling exhaust (1991-94), Oct.26
Batteries
diagnostics chart, Sep.51-52
solderless crimping of cables, Nov.14, 16
Bearings, CV joints & U joints
diagnostic chart, Feb.37
diagnostics using infrared thermometers, Mar.25
Beck/Arnley Worldparts
2000 Rotating Electrical Catalog, Feb.73
master catalog, Oct.30
new filter catalog, Jan.64
Remanufactured Ignition Distributors brochure, Mar.89
Bendix Brakes, new merchandising materials, Sep.77
Beretta (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
new diagnostic tables (1996), Feb.69
Bergwall Productions, ASE test prep guides, Jun.76
BizAutomation.com, e-commerce business system, Mar.89
Blazer (Chevrolet), inoperative heated front passenger seat (1998), Aug.59
Blue Streak Electronics, BDM Diagnostic Monitor, Sep.27
BMW
see also specific models
National Highway Safety Administration (NHTSA), battle over VIN code changes, Jan.57
replacing receiver/dryers, Jun.70
BMW Group, new Mini launched worldwide, Apr.51
Bonneville (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Bosal, import exhaust parts catalog, Aug.62
Bosch, new alternator design, May.22, 24-25
Boxster (Porsche)
power steering belt squeal (1997), Jul.71-72

2000 Motor Magazine Index

squeaky pedals (1997 on), Mar.85
Brake Align, Runout Correction Plates, Jun.79
Brake systems
see also Antilock brake systems (ABS)
diagnostics using infrared thermometers, Mar.25
isolating lockup problems, Mar.6-7
OE Scheduled Maintenance Handbook Tech Tips
brake fluid, Feb.31, 33
pads, shoes, drums, rotors, hoses & lines, Feb.33
Brake Tru, RotorResurfacers on-car rotor resurfacers, Jul.75
Bravada (Oldsmobile)
4.3-liter
dead battery, alternator not charging (1998), Jun.74
ticking noise underneath (1997-98), Jul.70
5-liter, ticking noise underneath (1997-98), Jul.70
7.4-liter, ticking noise underneath (1997-98), Jul.70
inoperative heated front passenger seat (1998), Aug.59
Breeze (Plymouth)
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
Bronco (Ford), PCM reprogramming flash cable available (1996), Feb.72
Business Sense
Getting to Know You questionnaire, Jun.47
keeping qualified technicians, Jun.45-48
knowing what your competition is doing, Sep.57-60
marketing strategies, Mar.71-74
Selling Diagnostic Time Profitably, Dec.39-42
BWD Automotive
1999 fuel pump applications catalog, Sep.77
Brute Power clutch kit program, Nov.80
Check Engine Light Training program, Feb.73
Remanufactured Electronic Components catalog, May.79
website address, Feb.73

C

C-Class (Mercedes-Benz)
2001 Import Tech Roundup, Dec.32
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
C/K-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
brake pull and premature front pad wear (1992-99), May.70-71
climate control knobs spin (1996-97), Jul.73
clutch pedal separates (1997), Sep.68
fuel gauge fluctuation (1995-97), Oct.28
rear axle leak (1992-96), Dec.50
"shrinking" gas tank (1995-97), Nov.75
C70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
Cab Chassis (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Cabrio (Volkswagen)
incorrect spark plug application listings (1991 on), Jun.62
oil overfill caution (latest generation), Dec.52
Cabriolet (Audi), MIL on, various EGR DTCs (1995), Sep.75
CAFE see Corporate Average Fuel Economy (CAFE)
California Air Resources Board (CARB), electric vehicle study results, Jul.61
California Fuel Cell Partnership, Honda joins, Jan.56-57
Camaro (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, spark knock at idle (1995-96), Dec.52
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1998-99), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
engine miss, poor driveability (1993-97), Jun.63
Camry (Toyota)
3-liter, DTC P1133, MIL illuminated (1997-99), Nov.79
poor driveability when cold (1988-89), Mar.84
steering gear service precaution (1996 newer), Dec.50
Caprice (Chevrolet), engine miss, poor driveability (1994-96), Jun.63
Car Care Council, contact information, Aug.46
Car Care Parts Mfg.
a/c compressor lifetime warranty, Jan.64
CD-ROM temperature control product catalog, Jan.64
website address, Jan.64
Caravan (Dodge)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
2001 model unveiled at 2000 North American International Auto Show, Mar.80-81
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
Cardone Industries
automotive electronics line expanded, Aug.62
website address, Aug.62
CARQUEST Auto Parts
1999 Excellence Award winner, Feb.73
Automotive Career Education Day, Jan.64
CCAR & Automotive Career Education Day (ACED), Jul.74
IHRA Sponsor of the Year, Mar.89
Special Olympics Gold Medal Sponsor, Jun.75
Underhood Sales Force expanded, May.79
CarStation.com, ARAcclerator PARTSonline recycler-to-recycler parts locator website, Jun.75
Cash in on America's Favorite Tools promotion, Jun.75
Castrol
redesigned website, Jul.74
Syntec Power System fuel system cleaner, Jun.76
Catalytic converters, diagnostics using infrared thermometers, Mar.25-26
Catera (Cadillac), evap system leak (1997), Apr.57-58
Cavalier (Chevrolet)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1996-97), Feb.69
Celica (Toyota)
steering gear service precaution (1996 newer), Dec.50
surging idle (1988-93), Jan.20, 22
Central Port Injection (CPI) system
common problems, Jul.22-23
EGR valve problems, Jul.23-24, 26
Century (Buick)
2.5-liter, intermittent no start, Jan.12, 15-16
3.1-liter, premature cranking with new PCM (1997), Apr.58
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, premature cranking with new PCM (1997), Apr.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
shaking sensation on smooth roads (1997-99), Oct.26
wipers don't park correctly (1997-98), Jun.69
CERCLA see Comprehensive Environmental Response, Compensation and Liability Act (CERCLA)
Challenger Lifts
new website, May.79
Versymmetric above-ground lift, Jun.76
Chart Industries, Twinn-Lift Tech-Centre, Sep.30
Cherokee (Jeep)
4-liter, scraping noise in engine compartment, radiator leak (1998), Sep.76
false MIL with various DTCs (1997), Nov.79
headlight flicker (1997-99), May.78
PCM reflashing tips (1995-99), Dec.50
radiator replacement for right hand drive, Aug.23
scraping noise under hard braking (1993-97), Dec.52, 56
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1995-99), Mar.84-85
Chicago Rawhide, Universal Joints Catalog for Passenger Car, Light, Medium and Heavy Duty Truck Applications, Nov.80
Chrysler
see also specific models
2000 Light Truck Service Report, Jan.41-42
a/c odor (prior to 1998), Jun.62
41TE/42LE transaxle, a/c bump, DTC 73 caused by TCC chatter (1996), Aug.60
minivans 2001 Domestic Tech Preview, Nov.28, 30
product liability lawsuit dismissed, Jun.59
Tomco
replacement aftermarket choke pinion gear, Jun.76
replacement MAP sensor (1987-90), Aug.66
unveils 2001 Sebring, Jul.61
Cirrus (Chrysler)
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
Civic (Honda)
2001 Import Tech Roundup, Dec.29-30
3.0-liter, mysterious oil pan-to-block leakage, Oct.14, 18
bad voltage regulator (1997-98), Jun.70
engine and dash warning lights fail when ignition key released (1996-97), Jul.14
frozen condenser fan (1996-98), Feb.70-71
CL (Acura), 2001 Import Tech Roundup, Dec.30-32
Classicar.com, new website, Feb.73
Clean Air Network, protest dropping Florida emissions tests, Jul.63, 65
Clevite Engine Parts
contact information, Jun.75
new piston ring design, Jan.56
training seminars, Jun.75
Victor Reinz master gaskets catalog, Oct.30
Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), fines for clean-up of used oil, Jan.49
Computers
see also Internet; Software
Ford, Worldwide Diagnostic System (WDS), ahead of schedule, Apr.51, 53
on-board computer software adds greater safety features to new vehicles, Sep.22, 24
Concept vehicles
2000 North American International Auto Show
24-7 (Ford), Mar.76
300 Hemi C (Chrysler), Mar.75-76
H1 (Hummer), Mar.76
H2 (Hummer), Mar.76
LaCrosse (Buick), Mar.76-77
MAXXcab (Dodge), Mar.75
Sprocket (Honda), Mar.79-80
SSR (Chevrolet), Mar.77
Terradyne (GMC), Mar.77
Varsity (Jeep), Mar.75
Viper GTS/R (Dodge), Mar.76
XVL (Infiniti), Mar.77
Concorde (Chrysler)
a/c leak (1995-97), Nov.79
2.7-liter, noisy tensioner (1998), Nov.78
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
new transmission software (1996-97), Apr.59-60
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Concours (Cadillac), oil ring installation revision (1994-97), Aug.61
Consider the Source, MOTOR Magazine Source Guide on-line, Jan.52-53
Contact East, updated fall electronic systems tools and equipment catalog, Jan.64
Contact information
addresses
Environmental Protection Agency (EPA), Jan.45
National Institute for Automotive Service Excellence (ASE), Jun.42
Safety-Kleen, Jan.46
The Learning Channel (TLC) Junkyard Wars, Jun.75
email addresses, Motorist Assurance Program (MAP) president, Jun.42
hotlines
Filter Manufacturers' Council, Jan.49
Ozone Protection Hotline, Mar.4
Resource Conservation and Recovery Act (RCRA), Jan.45
telephone numbers
Automotive Aftermarket Industry Association (AAIA), Sep.66
Automotive Lift Institute (ALI), Jul.74, Nov.80
Automotive Management Institute (AMI), Oct.30
Car Care Council, Aug.46
Clevite Engine Parts, Jun.75
Environmental Protection Agency

(EPA), Jan.45
Federal-Mogul, Jul.74
Guerrilla Diagnostics, Oct.30
Jazz Designs, Jul.74
Motorist Assurance Program (MAP), Jun.42, Sep.77
NAPA Institute of Automotive Technology (N.I.A.T), Aug.62
National Institute for Automotive Service Excellence (ASE), Jun.42, Aug.46
Safety-Kleen, Jan.46
Scott Specialty Gases, Oct.30
Toyota Racing Development, Jul.74
Visteon, Jul.74
Continental (Lincoln)
ABS noise (1998-99), Jun.74
automatic transmission identification (1988-96), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
Moog Automotive, improved non-greasable front stabilizer bar link (1988-94), Apr.54
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
popping noise in front end (1988-94), Jan.60
ticking noise from transaxle (1995), Mar.86
transmission DTCs stored in memory (1998), May.76
Continental-Teves, Electronic Stability Program (ESP), Sep.24
Contour (Ford)
2.5-liter, MIL on, DTCs stored (1996-98), Jul.72-73
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-99), Feb.72
Contour SVT (Ford), steering pull/drift to the right (1998-99), Oct.26
Cooling systems
see also A/C systems; HVAC systems
bleeding Nissan transverse cooling system, Apr.4-5
cooling tips from NARSA, Aug.22-27
diagnostics using dynamometers, Nov.44-45
diagnostics using infrared thermometers, Mar.23-24
filling the system, Aug.25-27
NARSA cooling tips, Aug.22-27
OE Scheduled Maintenance Handbook Tech Tips, Feb.35
pressure testers, Aug.23-24
radiators, Aug.22
thermostats, Aug.24-25
using your shop's water heater to test radiator core temperature, Aug.6
Cooling Tips From NARSA, Aug.22-27
Corolla (Toyota)
steering gear service precaution (1996 newer), Dec.50
surging idle (1987-93), Jan.20, 22
Corporate Average Fuel Economy (CAFE)
see also Fuel economy
economy standards loophole, Mar.14, 16, 19
Corrado (Volkswagen), 2.8-liter, rough idle, poor performance (1992-94), Mar.85
Corrado SLC (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Corsica (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
new diagnostic tables (1996), Feb.69
Corvette (Chevrolet)
2001 Domestic Tech Preview, Nov.25-26
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1997-99), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
engine miss, poor driveability (1992-96), Jun.63
higher-than-normal temperature gauge reading (1994), Jun.4, 6
non-linear analog temperature gauge (1990-96), Aug.4, 6
Cougar (Mercury)
3.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
4.6-liter, PCM reprogramming flash cable available (1994-97), Feb.72
blower motor squeak/chirp (1989-97), Aug.58, Nov.78
delayed upshift from reman 4R70W (1994-97), Aug.59
PCM reprogramming flash cable available (1999), Feb.72
transmission DTCs stored in memory (1997), May.76
Coxreels, Poly-Pro hose reels, Dec.65
CPI see Central Port Injection (CPI) system
CR-V (Honda), clunking from power windows (1997-98), Jul.71
Crankcase sensors see under Sensors
CRC Industries, acquires K&W Acquisition Group, Jan.64
Crew Cab (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Crown Entertainment Racing Team, 1956 Ford Crown Victoria IHRA funny car, Mar.28-30
Crown Remanufacturing
remanufactured power steering pumps, Aug.66
Vintage Parts program, Feb.73
website address, Feb.73, Dec.64
Crown Victoria (Ford)
4.6-liter, no crank (1992-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
stall during acceleration and/or turning (1996), Jun.65-66
transmission DTCs stored in memory (1998), May.76
Cuda Cleaning Systems, H20-2518V automatic parts washer, Oct.36
Curing the Fuel Injector Blues, General Motors Central Port Injection (CPI) fuel injection system, Jul.20-24, 26
Cutlass (Oldsmobile)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.4-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1997), Feb.69
Cutlass Ciera (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
Cutlass Cruiser (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Cutlass Supreme (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
CV joints see Bearings, CV joints & U joints
Cyclo Industries, Anti-Gel Diesel Fuel Treatment, Sep.78
Cylinder heads, troubleshooting & service procedures for leaks, Aug.23-40

D

DAB see Digital Audio Broadcasting (DAB)
DaimlerChrysler Corp.
Covisint, automotive Internet exchange, Jun.56, 58
Freightliner Division purchases Western Star, Sep.64
leaves Global Climate Coalition (GCC), Apr.53
Dakota (Dodge)
3.9-liter, ignition crossfire (1994-99), Feb.71-72
4.7-liter, new 45RFE transmission explained, Jun.35-38
5.2-liter, ignition crossfire (1994-99), Feb.71-72
5.9-liter, ignition crossfire (1994-99), Feb.71-72
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
Dakota Quad Cab (Dodge), 2000 Light Truck Service Report, Jan.41-42
DATEC, Coil On Plug-II Ignition Tester, Sep.40
Daytona (Dodge), intermittent cruise control (1990-93), Oct.28
DCi see Direct Communications, Inc (DCi)
dealerHQ.com, new automotive careers website, Feb.73
Defender (Land Rover)
3.9-liter, hard start in cold weather (1993-95), May.73
O2 sensor codes (1997), Feb.69-70
Del City
electrical parts website, Oct.30
electrical products catalog, Dec.64
Delphi, new alternator design, May.22, 24-25
Denso, new alternator design, May.22, 24-25
Department of Environmental Quality (DEQ), partners with Automotive Service Association (ASA), Feb.63
DEQ see Department of Environmental Quality (DEQ)
DeVille (Cadillac)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
intermittent Neutral on the highway (1995), Sep.73
leaky oil cooler lines (1993-98), Dec.52
oil ring installation revision (1994-97), Aug.61
DeVille D'Elegance (Cadillac), oil ring installation revision (1997), Aug.61
Diagnosing Electronic Climate Control Actuators, Apr.32-34, 36-38
Diagnosing Those Maddening Misfires, investigating the Misfire Monitor, May.27-30, 32, 36
Diagnostics
see also Diagnostics Kept Simple; Driveability Corner
confusing misfire info from the MIL, May.30, 32, 36
electronic climate control actuators, Apr.32-34, 36-38
investigating the Misfire Monitor, May.27-30, 32, 36
Scan Data: How Much is Too Much?, May.40-42, 44, 46-47
Selling Diagnostic Time Profitably, Dec.39-42
using a current probe and scope, ABS, Jun.26-28, 30-31
using a graphing multimeters for intermittents, Sep.42-47
using dynamometers, Nov.44-47
using infrared thermometers
automatic transmission systems, Mar.25
bearing, CV joints & U-joints, Mar.25
brake systems, Mar.25
catalytic converters, Mar.25-26
cooling systems, Mar.23-24
EGR valve, Mar.26
engine misfire, Mar.25
HVAC systems, Mar.25
important instrument features, Mar.26
intake air temperature regulation, Mar.26
rear differential, Mar.26
tires & alignment, Mar.26
underhood thermal mapping, Mar.26
Diagnostics Kept Simple
see also Diagnostics; Driveability Corner
battery goes dead, Sep.49-52
diagnostic chart
battery goes dead, Sep.51-52
CV joint, Feb.37
engine does not crank, Feb.57-60, Apr.43-46
engine cranks but won't start, Jul.55-56, 55-60
engine does not crank, Feb.55-56, Apr.42-46
engine overheats, May.63-64
new series introduced, Feb.55-56
Diamante (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
Differentials see under Drivelines
Digital Audio Broadcasting (DAB), new technology explored, Jan.26
Direct Communications, Inc (DCi)
Internet-based service catalog, Jan.64
website address, Jan.64
Discovery (Land Rover)
3.9-liter
hard start in cold weather (1993-95), May.73
wrong ignition timing (1994), Apr.56
bad heater hose (1997), May.78
camshaft knock (1994-95), Jan.61-62
engine surge while coasting (1997), Oct.27
MIL on, DTC P0451 (1997 newer), Apr.64-65
O2 sensor codes (1996-98), Feb.69-70
Driveability Corner
diagnosing fuel delivery problems with a scan tool, Feb.14, 16
diagnostics using pre/post catalyst O2 sensors, Apr.16, 19, 21
diagnostics with 3-D mapping, Dec.20, 22
Odyssey (Honda), O2 sensor tests (2000), Oct.20, 22
using long-term/short-term fuel trim values to check fuel delivery volume, Aug.18, 20
using the MAF sensor to diagnose EGR system problems, Jun.20, 22, 24
Drivelines
binding slip-joints, Mar.21
diagnosing differential problems using infrared thermometers, Mar.26
diagnostics using dynamometers, Nov.45
differential, diagnostics with infrared thermometers, Mar.26
OE Scheduled Maintenance Handbook Tech Tips
automatic transmission fluid & filters, Feb.36
CV joints & boots, Feb.36-37
manual gearboxes, differentials & transfer cases, Feb.36
DuPont Automotive
automotive aftermarket website, Jan.64
refrigerants win Saturn Quality Achievement Award, Feb.73
DuPont Suva, 134a refrigerant wins award, May.79
Durango (Dodge)
3.9-liter, ignition crossfire (1998-99), Feb.71-72
4.7-liter, new 45RFE transmission explained, Jun.35-38
5.2-liter, ignition crossfire (1998-99), Feb.71-72

2000 Motor Magazine Index

5.9-liter, ignition crossfire (1998-99), Feb.71-72
bucking at wide open throttle (1998), Nov.76-77
PCM reflashing tips (1998-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
Dynamometers
diagnostic capabilities, Nov.46-47
safety considerations, Nov.47
systems, Nov.44
types, Nov.44
versatility of, Nov.44-46
Dynasty (Dodge), intermittent cruise control (1989-93), Oct.28
Dynos: More Than a Smog Check Machine, Nov.42-47

E

E-250 (Ford), 4.2-liter, exhaust booming noises (1997-98), Dec.52
E-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
Halogen/Xenon headlight repair kits (1996 on), May.71
E-Z Hook, XEL Test Connector, Jun.78-79
E420 (Mercedes-Benz), automatic transmission fluid caution (1996), Apr.64
EASE Diagnostics, Wireless Vehicle Interface, Sep.37-38
ECC see Electronic climate control (ECC) systems
Econoline (Ford)
4.2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.6-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
4.9-liter, PCM reprogramming flash cable available (1996), Feb.72
5-liter, PCM reprogramming flash cable available (1996), Feb.72
5.4-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
5.8-liter, PCM reprogramming flash cable available (1996), Feb.72
6.8-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
7.3-liter turbodiesel, PCM reprogramming flash cable available (1995-99), Feb.72
7.5-liter, PCM reprogramming flash cable available (1996), Feb.72
binding ignition key (1997-99), Nov.75
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, no symptoms (1997), Apr.63-64
steering column squeak/moan (1992-99), Jun.74
transmission DTCs stored in memory (1997-98), May.76
Editor's Report
California OBDII legislation closer to passing, Aug.2
e-commerce increase, Dec.4
Global Automotive Aftermarket Symposium (GAAS), Jun.2
good employer/employee communication, Nov.2
importance of preventive maintenance, Feb.2
increasing wages for automotive technicians, Apr.2
the Internet and the automotive industry, May.2
lessons about middle age and automobile industry, Jul.2
Mobile Air Conditioning Society (MACS), a/c survey results, Mar.4
MOTOR Magazine lawsuit against W.G. Nichols, Inc., Jan.2, 4
MOTOR'S Source Guide, Oct.4
post-warranty service, Dec.4
praise for the automobile aftermarket industry, Sep.4
receives 10th International Automotive Media Conference (IAMC) Silver Medallion award, Dec.62
technology increases, Dec.4
trends in the aftermarket industry, Dec.4
unfair competition in aftermarket, Jan.2, 4
website addresses for automotive industry, May.2
Education
see also Training
Check Engine Light education program, Feb.73
free used brake lathes for tech schools, Apr.66
scholarship established, May.79
setting goals and safety lectures, Mar.28-30
Tools for Schools program, Oct.30
two new Technical Education Centers, May.69
We Care environmental education program, Jan.45-46
EFI see Electronic fuel injection (EFI) systems
EGR systems
Accord (Honda)
2.2-liter, revised EGR system (1994-97), Jul.14
clogged passages, May.14, 16
diagnostics using infrared thermometers, Mar.26
Eidos Corp., GlydeMaster ergonomically designed creeper, Oct.36
Eighty Eight (Oldsmobile), intermittent Neutral on the highway (1995-97), Sep.73
Elantra (Hyundai)
revised TCMs (1996), Nov.75-76
timing chain noise (1996-98), Jun.68
Eldorado (Cadillac)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
leaky oil cooler lines (1993-98), Dec.52
oil ring installation revision (1993-97), Aug.61
Electric vehicles (EV)
see also Hybrid electric vehicles (HEV)
California Air Resources Board (CARB), electric vehicle study results, Jul.61
Electrical systems
assessment quiz, Nov.39-40
Ford readies for 42-volt system, Jun.51-52
troubleshooting electical accessories, Nov.35-38
Electronic climate control (ECC) systems
see under HVAC systems
Electronic fuel injection (EFI) systems
see also Fuel injection systems
air-flow controlled system, Aug.30
basic system parts, Aug.29-30
Engine Performance Assessment quiz, Aug.33-34
fuel metering, Aug.30
General Motors Central Port Injection (CPI) fuel injection system, Jul.20-24, 26
mass-airflow (MAF) system, Aug.30-31
port-fuel-injected (PFI)/throttle-body-injected (TBI) systems, Aug.31-32
speed-density system, Aug.30
troubleshooting basics, Aug.31-32
Electronic Stability Program (ESP), explained, Sep.24
Electrostatic discharge (ESD), minimizing the effects, Jul.16-18
Elgin Industries
80th anniversary engine, chassis and performance parts catalog, Jan.64
new chassis parts catalog, Sep.77
Email addresses see under Contact information
Emissions
avoiding the quick fix for failures, Apr.6, 10-11
diesel emissions linked to cancer, Feb.67
Dynos: More Than a Smog Check Machine, Nov.42-47
General Motors teams with BP on low-sulpher gasoline, Dec.60-62
Kolbenschmidt Pierburg, smart secondary air blower, May.67-68
new EPA truck and SUV regulations, Feb.66-67, May.68-69
Engine Connection, remanufactured engine, cylinder head, transmission catalog, Jul.74
Engine performance
Corvette (Chevrolet), diagnosing higher-than-normal temperature gauge reading (1994) with IR thermometer, Jun.6
cranks but won't start, Jul.55-56
diagnostic chart
cranks but won't start, Jul.57-60
does not crank, Feb.57-60, Apr.43-46
overheating, May.65-66
diagnostics using dynamometers, Nov.45
diagnostics using infrared thermometers, Mar.26
does not crank, Feb.57-60, Apr.42
Engine Performance Assessment quiz, Aug.33-34
OE Scheduled Maintenance Handbook Tech Tips
air filter & PCV valve, Feb.39, 41
fuel filter, cap & lines, Feb.43-44
O2 sensor, Feb.41-42
spark plugs & wires, Feb.39
timing belts, Feb.44-45
valve adjustments, Feb.42-43
overheating, May.63-64
Environmental Protection Agency (EPA)
contact information, Jan.45
diesel emissions linked to cancer, Feb.67
disposable refrigerant cylinder debate, Aug.55
disposal of used oil, Jan.46, 48
fuel economy report, Jan.57
Managing Used Motor Oil, Jan.45
Managing Used Oil, Advice for Small Businesses, Jan.45
new SUV & truck emissions standards, Feb.66-67, May.68-69
Spill Prevention Control and Countermeasures Regulations, Jan.45-46
Underground Storage Tank Regulations, Jan.45-46
Used Oil Management Standards, used oil recycling exemptions, Jan.49
website address, Mar.4
EPA see Environmental Protection Agency (EPA)
Equipment and Tool Institute (ETI)
new Gorman Technical Manager named, Apr.66
Trade Press Report, Nov.49-58, 60, 62, 64
ES 300 (Lexus), outside temperature reads -22o F (1993-96), Dec.56
ES 400 (Lexus), inaccurate outside temperature display (1995-96), Jun.69
Escape (Ford)
2001 Domestic Tech Preview, Nov.32
hybrid-electric vehicle (HEV), 2003 debut, May.67
Escort (Ford)
1.9-liter, PCM reprogramming flash cable available (1996), Feb.72
2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
blower motor squeak/chirp (1991-97), Aug.58, Nov.78
brake noise (1997-99), Jul.68
front brake knocking noise (1991-96), Oct.28
Escort ZX2 (Ford), brake noise (1998-99), Jul.68
ESD see Electrostatic discharge (ESD)
Ethanol see Fuels
ETI see Equipment and Tool Institute (ETI)
Eurovan (Volkswagen)
axle shaft service (all years), May.77-78
modified cam drive chain (1997 and on), May.72
oil overfill caution (latest generation), Dec.52
EV see Electric vehicles (EV)
Excel 2000, Automotive Management Institute, resource development program, Apr.66
Excursion (Ford), 2000 Light Truck Service Report, Jan.39-40
Exhaust systems, OE Scheduled Maintenance Handbook Tech Tips, Feb.34
Expedition (Ford)
4.6-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
high idle, sticking throttle (1997-98), May.72-73
5.4-liter, high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
ABS light on (1997-99), Oct.24
air suspension light on (1997-99), Jun.69
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1997-99), Feb.72
transmission DTCs stored in memory (1998), May.76
Explorer (Ford)
4-liter
acceleration "whoosh" (1997), Jun.61
hesitation, harsh downshift (1997-99), Jan.62-63
5-liter, hesitation, harsh downshift (1997-99), Jan.62-63
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, DTCs, O2 sensor leak (1996-98), Dec.56
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
Explorer Sport (Ford), 2000 Light Truck Service Report, Jan.40
Explorer Sport-Trac (Ford), 2000 Light Truck Service Report, Jan.40
Express (Chevrolet), 4.3-liter, slower-than-normal downshifts (1997), Jun.66
Exxon Mobil, Drive Clean Blend synthetic motor oil, Oct.36
Eye on Electronics
Continental-Teves, Electronic Stability Program (ESP), Sep.24
inherent problems with Flexible Fuel vehicles, Mar.14, 16, 19
innovations in stereo systems, Jan.26-29
minimizing the effects of electrostatic discharge (ESD), Jul.16-18
new alternator design, May.22, 24-25
O2 sensor replacement intervals, Nov.20-22
sensors, computers add greater safety features on new vehicles, Sep.22-24
Thunderbird (Ford), black smoke, poor fuel economy (1988), Nov.20-22

F

F-150 (Ford)
2000 Light Truck Service Report, Jan.39
4.6-liter, high idle, sticking throttle (1997-98), May.72-73
ABS light on (1997-99), Oct.24
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69,

Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
transmission DTCs stored in memory (1997-98), May.76
F-250 (Ford)
4.6-liter, high idle, sticking throttle (1997-98), May.72-73
fuel pump service tip (1998), Sep.70, 72
F-250 HD (Ford), stall after long deceleration (1997), Sep.74-75
F-250 LD (Ford)
ABS light on (1997-99), Oct.24
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
transmission DTCs stored in memory (1997-98), May.76
F-350 (Ford), stall after long deceleration (1997), Sep.74-75
F-Series (Ford)
4.2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.6-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.9-liter, PCM reprogramming flash cable available (1996), Feb.72
5-liter, PCM reprogramming flash cable available (1996), Feb.72
5.4-liter, PCM reprogramming flash cable available (1997-99), Feb.72
5.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
6.8-liter, PCM reprogramming flash cable available (1999), Feb.72
7.3-liter turbodiesel, PCM reprogramming flash cable available (1994-99), Feb.72
7.5-liter, PCM reprogramming flash cable available (1996-97), Feb.72
FCX (Honda), fuel cell vehicle, unveiled at 2000 North American International Auto Show, Mar.79-80
Federal-Mogul
awards to NHRA Sportsman competitors, Mar.89
contact information, Jul.74
continued support for NHRA drag racing, Aug.62
Moog Late Model Master Chassis Catalog, Nov.80
ON TRACK! campaign extended, Jul.74
two new Technical Education Centers, May.69
Ferret Instruments
automotive testing and diagnostic equipment catalog, Jul.74
Top Twenty Tools, Ferret 55 EngineLink Diagnostic Analyzer, Sep.34-35
FFV see Flexible Fuel Vehicles (FFV)
Filter Manufacturers' Council, hotline, Jan.49
Filters
air, OE Scheduled Maintenance Handbook Tech Tips, Feb.39, 41
fuel, OE Scheduled Maintenance Handbook Tech Tips, Feb.43-44
oil, OE Scheduled Maintenance Handbook Tech Tips, Jan.47-49
Firebird (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, spark knock at idle (1995-96), Dec.52
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1998-99), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
engine miss, poor driveability (1993-97), Jun.63
FirstStrike, marketing components, Jun.75
Fleetwood (Cadillac), engine miss, poor driveability (1994-96), Jun.63
Flexible Fuel Vehicles (FFV), inherent problems in, Mar.14, 16, 19
Florida
Bureau of Petroleum Inspection, random antifreeze inspections, May.68
considers elimination of emissions inspections, Apr.53
environmentalists protest dropping emissions tests, Jul.63, 65
Ford
see also specific models
2000 Light Truck Service Report, Jan.38-41
Covisint, automotive Internet exchange, Jun.56, 58
heavy-duty radiator alternatives for medium duty trucks with Cummins engines, Aug.23
joins Qualcomm to create Wingcast wireless mobility and information services, Sep.66-67
new safety features, unveiled at 2000 North American International Auto Show, Mar.79
proper grade of motor oil (1989 on), Sep.70
readies for 42-volt systems, Jun.51-52
teams up with Yahoo!, Mar.76
TH!NK City, environmentally mobile division, Mar.78-79
Tomco Pressure Feedback EGR Sensor (1986-94), Jul.75
voice-activated Telematics systems, Internet access, Mar.76
Worldwide Diagnostic System (WDS) ahead of schedule, Apr.51, 53
Foreign Service
4Runner (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
surging idle (1988-94), Jan.20, 22
Accord (Honda)
2.2-liter
clogged EGR passages (1990 newer), May.14, 16
finding the fast-idle valve (1995), Jul.14-15
revised EGR system (1994-97), Jul.14
cracking rubber in harmonic balancer (1990-93), Aug.14, 17
engine and dash warning lights fail when ignition key released (1990-93), Jul.14
Altima (Nissan), diagnosing oil leaks (1993-98), Sep.16, 20-21
Celica (Toyota), surging idle (1988-93), Jan.20, 22
Civic (Honda)
3.0-liter, mysterious oil pan-to-block leakage, Oct.14, 18
engine and dash warning lights fail when ignition key released (1996-97), Jul.14
Corolla (Toyota), surging idle (1987-93), Jan.20, 22
FX16 (Toyota), surging idle (1987-91), Jan.20, 22
Honda
diagnosing a bad fast-idle valve, Apr.12, 15
idle speed control system problems, Jun.16, 18
new tricks for pulling codes from diagnostic connector, Jun.18
MR2 (Toyota), surging idle (1987-91), Jan.20, 22
Paseo (Toyota), surging idle (1990-94), Jan.20, 22
Prelude (Honda), cracking rubber in harmonic balancer (1988-91), Aug.14, 17
Previa (Toyota), surging at cruise (1991-92), Jan.22
solderless crimping of battery cables, Nov.14, 16
T100 (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
Tacoma (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
Tercel (Toyota), surging idle (1990-94), Jan.20, 22
Toyota
binding driveshaft slip-joints, Mar.21
MAP sensor testing, Mar.20-21
O2 sensor flange gasket leakage, Mar.21
troubleshooting throttle openers, fast-idle valves, throttle position sensors (TPS), Jan.20, 22
Truck (Toyota)
misleading sensor signals (late 80s-early 90s), Feb.18, 21
surging idle (1988-94), Jan.20, 22
Tundra (Toyota), 3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
Fuel cell vehicles
A Glimpse at Fuel Cell Vehicles, Dec.44-46
2000 North American International Auto Show
FCX (Honda), Mar.79-80
Precept (General Motors), Mar.79
Fuel economy
see also Corporate Average Fuel Economy (CAFE)
Environmental Protection Agency (EPA) report, Jan.57
National Highway Traffic Safety Administration (NHTSA), US fuel economy report, Nov.69-70
Saab Combustion Control (SCC) System, Dec.58-60
Fuel injection systems
see also Electronic fuel injection (EFI) systems
diagnosing the GM Central Port Injection (CPI) system, Jul.20-24, 26
Fuel systems
diagnosing fuel delivery problems with a scan tool, Feb.14, 16
scheduled maintenance, Feb.43-44
using long-term/short-term fuel trim values to check fuel delivery volume, Aug.18, 20
Fuels
General Motors teams with BP on low-sulpher gasoline, Dec.60-62
senate hearing debates ethanol, Aug.57
FX16 (Toyota), surging idle (1987-91), Jan.20, 22
F.Y.I.
Airtex Products
Fall/Winter Bounty Program, Oct.30
fuel pumps pass NASCAR quality standards, Jan.64
All Pro/Bumper to Bumper
joins Automotive Service Association (ASA), Feb.73
You Drop the Flag promotion, Jun.75
ALLDATA, 2000 database, Jun.75
AlliedSignal, two new brake catalogs, Feb.73
American Remanufacturers
CV axle components catalog, Aug.62
remanufactured brake component catalog, May.79
Amsoil, Spring, 2000 product catalog, Jun.75
ARA Services, ARAccelerator PARTSonline recycler-to-recycler parts locator website, Jun.75
Association for Career and Technical Education, Automotive Awards of Excellence winners, Feb.73
Auto Value Associates, Advanced Counterpoint Training Series, May.79
AUTOdealerjobs.com, new automotive careers website, Feb.73
Automotive Aftermarket Industry Association (AAIA)
association directory, Aug.62
survey participants needed, Jun.75
Automotive Aftermarket Industry Week (AAIW), website address, Sep.77
Automotive Engine Rebuilders Association (AERA), online marketplace, Sep.77
Automotive Leadership Institute, AMI certified shop management training courses, Sep.77
Automotive Lift Institute (ALI)
ANSI/ALI ALOIM-2000 safety requirements, Nov.80
member company directory, Sep.77
Vehicle Lifting Points for Frame Engaging Lifts, Jul.74
Automotive Management Institute (AMI), management seminars, Oct.30
Automotive Parts Rebuilders Association (APRA)
CV & Racks Clinic, Apr.66
e-commerce website, Jan.64
Volume Transmission Clinic, Apr.66
Automotive Service Association (ASA), partners with GreatMechanics.com, Apr.66
Automotive Video, Inc., Five Days of Thunder training seminar, Oct.30
Autovia, new manufacturer catalogs added to online database, Oct.31
AVM, StrongArm 2000 Application & Buyer's Guide, May.79
Beck/Arnley Worldparts
2000 Rotating Electrical Catalog, Feb.73
master catalog, Oct.30
new filter catalog, Jan.64
Remanufactured Ignition Distributors brochure, Mar.89
Bendix Brakes, new merchandising materials, Sep.77
BizAutomation.com, e-commerce business system, Mar.89
Bosal, import exhaust parts catalog, Aug.62
BWD Automotive
1999 fuel pump applications catalog, Sep.77
Brute Power clutch kit program, Nov.80
Check Engine Light training program, Feb.73
fuel injection parts catalog, Jul.74
Remanufactured Electronic Components catalog, May.79
Car Care Parts Mfg.
a/c compressor lifetime warranty, Jan.64
CD-ROM temperature control product catalog, Jan.64
Cardone Industries, automotive electronics line expanded, Aug.62
CARQUEST Auto Parts
1999 Excellence Award winner, Feb.73
Automotive Career Education Day, Jan.64
CCAR & Automotive Career Education Day (ACED), Jul.74
IHRA Sponsor of the Year, Mar.89
Special Olympics Gold Medal Sponsor, Jun.75
Underhood Sales Force expanded, May.79
CarStation.com, ARAccelerator PARTSonline recycler-to-recycler parts locator website, Jun.75
Castrol, redesigned website, Jul.74
Challenger Lifts, new website, May.79
Chicago Rawhide, Universal Joints Catalog for Passenger Car, Light, Medium and Heavy Duty Truck Applications, Nov.80
Classicar.com, new website, Feb.73
Clevite Engine Parts, training seminars, Jun.75
Contact East, updated fall electronic systems tools and equipment catalog, Jan.64
CRC Industries, acquires K&W Acquisition Group, Jan.64
Crown Remanufacturing
new website, Dec.64
Vintage Parts program, Feb.73
dealerHQ.com, new automotive careers website, Feb.73
Del City
electrical parts website, Oct.30
electrical products catalog, Dec.64
Direct Communications, Inc (DCI), Internet-based service catalog, Jan.64
DuPont Automotive
automotive aftermarket website, Jan.64
refrigerants win Saturn Quality Achievement Award, Feb.73
DuPont Suva, 134a refrigerant wins award, May.79
Elgin Industries
80th anniversary engine, chassis and performance parts catalog, Jan.64
new chassis parts catalog, Sep.77
Engine Connection, remanufactured engine, cylinder head, transmission catalog, Jul.74
Equipment and Tool Institute (ETI), new Gorman Technical Manager named, Apr.66

2000 Motor Magazine Index

Federal-Mogul
awards to NHRA Sportsman competitors, Mar.89
continued support for NHRA drag racing, Aug.62
Moog Late Model Master Chassis Catalog, Nov.80
ON TRACK! campaign extended, Jul.74
Ferret Instruments, automotive testing and diagnostic equipment catalog, Jul.74
FirstStrike, marketing components, Jun.75
Gates Rubber, Molded Coolant Hose Locator Guide, Mar.89
Gray Automotive, jack and lifting equipment catalog, Apr.66
Guerrilla Diagnostics, Advanced Honda PCM-FI/OBDII diagnostics training, Oct.30
Hannay Reels
hose reel catalog, Mar.89, Dec.64
reference guide, Oct.31
Hennessey Industries, Internet e-zine Shop Smarts, Sep.77
Honeywell Friction Materials, expanded RoadTuff brake products line, Aug.62
Hunter Engineering
RL Alignment Lift Rack brochure, Jul.74
website address, Mar.89
Hydro-Blast, aqueous conveyor washer CD, Dec.64
iCARumba, INSITE free website and hosting package, Nov.80
International Lubricants, OE Scheduled Maintenance Handbook Tech Tips/Testimonials section added to website, Dec.64
Jazz Designs, AUTOS2000 Automotive Shop Management new software features, Jul.74
Jendham
GM ABS clinic, Apr.66
On-Line Scan Tool Comparison Guide, Jul.74
K&W Acquisition Group, acquired by CRC Industries, Jan.64
Kaeser Compressors, Designing Your Compressed Air System, Mar.89
Lease2save.com, Inc., lease proposal website, May.79
Lincoln Electric, free wall chart, Oct.31
LKQ Corp., free parts replacement guarantee, Mar.89
Lubrimatic, grease gun brochure, Jun.75
McQuay-Norris, chassis component catalog, Nov.80
Miller Electric Mfg., welding and plasma cutting product catalog, Mar.89
Modine
AirPro Quality Parts catalog, Jul.74
Lifetime Protection Free! poster & counter card, Nov.80
Mopar Parts, longer warranty on remanufactured powertrain components, Sep.77
Motorist Assurance Program (MAP), Uniform Inspection & Communication Guidelines (UICG) Internet-based training program, Sep.77
MotorVac Technologies, MV4 Air Intake & Throttle Body Cleaner, May.79
NAPA/ASE Technician of the Year, Dec.64
NAPA Chassis, vehicle alignment and chassis components promotion, Jan.64
NAPA Institute of Automotive Technology (N.I.A.T.), earns Continuing Automotive Service Education (CASE) certification, Aug.62
NAPA Rayloc, helps fund scholarship program, Nov.80
NAPA United, power brake booster catalog, Dec.64
NASCAR, NASCAR. Your Car promotion, Jan.64
Nickson Industries, exhaust gasket catalog and application guide, Aug.62
Nylok Fastener, new NYTEMP brochure, Apr.66
Osram Sylvania, Automotive Lamp Replacement Guide on website, Oct.30
PageViews, marketing website, Nov.80
Popular Mechanics, Tools for Schools program, Oct.30
Prestolite Wire, acquired Speed Clip Division of Exide Corp., Feb.73
Pro-Cut International
free used brake lathes for tech schools, Apr.66
website address, May.79
Raybestos Brakes
domestic and import brake parts catalog, Jan.64
Electric Trailer Brake Catalog, Jun.75
loaded calipers carry D3EA certification, Feb.73
new Quiet Stop products added, Oct.31
updated Brake and Safety Center program, Apr.66
Robinair, updated website, Feb.73
Rotary Lift
75th anniversary celebration, Mar.89
automotive lift brochure, Jun.75
Inground Lift Replacement Program, May.79
The Lift Buyer's Bible, Jan.64
updated and redesigned website, Aug.62
RTI Technologies, Midas preferred supplier, Mar.89
Safe Shop Tools, safe tool catalog, Apr.66
Safety-Kleen
AquaWorks-The Power of Water brochure, Jul.74
CabPak chemical management, storage, packaging and disposal program, Mar.89
Compliance Solutions: Compliance You Need...When You Need It, May.79
Service Technicians Society (STS), employment section added to website, Dec.64
Siemens Automotive, Daimler Chrysler CHEER Award received, Mar.89
SK Hand Tool, website, Mar.89
Snap-on Tools
pledge to Automotive Management Institute's Excel 2000 program, Apr.66
product line available on line, Nov.80
SPX, Cash in on America's Favorite Tools promotion, Jun.75
Swapman.com, selling excess automotive parts, Jan.64
The Learning Channel (TLC), Junkyard Wars team search, Jun.75
Titan Tool Supply, optical inspection equipment catalog, Apr.66
Tomco
4 Will Get You 1 brochure assortment, Nov.80
fuel and emissions parts catalog, Feb.73, Aug.62, Oct.31
fuel and emissions systems brochures, Dec.64
Toyota Racing Development, parts, performance data, reference guides, application charts catalog, Jul.74
Tracer Products, Tracerline leak detection products brochure, Dec.64
University of the Aftermarket, joins Northwood University, Dec.64
Visteon
ClimatePro Air Conditioning Components Applications Catalog and Illustrated Guide, Jul.74
ClimatePro Heat Transfer Components Applications Catalog and Illustrated Guide, Jul.74
Visteon Automotive Systems, scholarship established, May.79
Volvo Tech Tips, flyers, Oct.30
Wal-Mart, Tools for Schools program, Oct.30
Waterloo Industries, tool storage products catalog, Dec.64
WIX Filtration Products
Future Farmers of America contribution, Jan.64
NASCAR and NHRA racing contract extensions, Apr.66
Wrenchead.com, Inc., Wrenchead Pro turnkey business-to-business system, Sep.77

G

G-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
brake pull and premature front pad wear (1996-99), May.70-71
climate control knobs spin (1996-97), Jul.73
G20 (Chevrolet)
ongoing screeching brake problem (1996), May.4, 7
screeching noise when braking (1996), Jan.6, 11
GAAS see Global Automotive Aftermarket Symposium (GAAS)
Galant (Mitsubishi), coolant service (1994-96), Jan.63
Gasoline see Fuels
Gates Rubber
Molded Coolant Hose Locator Guide, Mar.89
updated Timing Belt Replacement Manual, Aug.66
GCC see Global Climate Coalition (GCC)
General Motors
see also specific models
2000 Light Truck Service Report, Jan.37-38
automatic headlights and DRL retrofits (1996 and older with some exceptions), Nov.78-79
Central Port Injection (CPI) fuel injection system, Jul.20-24, 26
Covisint, automotive Internet exchange, Jun.56, 58
evaporator odor in all cars and light duty trucks except Geo and Tracker, May.75
exterior light leakage/condensation (1993-99), Feb.72
high-temperature systems, Aug.24
Honda/OnStar/XM Satellite Radio team up to offer mobile communication services, Jul.62-63
hybrid powertrain in full-size truck, Sep.64, 66
Internet B2B e-commerce alliance formed, Apr.49
new PCM connector service kits (1996-99), Mar.88
stability control, Nov.27
teams with BP on low-sulpher gasoline, Dec.60-62
vans reworked for handicapped, Nov.28
wrong PCV maintenance schedules (1994-98), Aug.60
General Motors Performance Parts, Ram Jet 350 small block engine, Jul.61-62
Gent-L-Kleen
Orange Hand Cleaner, comparison, Jul.34
Zapper Paint & Resin Remover, comparison, Jul.34
Genuine Parts, Internet B2B e-commerce alliance formed with Snap-on, Apr.50
Global Automotive Aftermarket Symposium (GAAS), Jun.2
Global Climate Coalition (GCC), DaimlerChrysler Corp. leaves, Apr.53
GM Good Wrench Service Plus, website address, Jul.62
GOJO Hand Care System
Fast Wipes, comparison, Jul.34
Hand Medic, comparison, Jul.34
Hand Pro, comparison, Jul.34
Paint & Stain Remover, comparison, Jul.34
Power Gold, comparison, Jul.34
Supro, comparison, Jul.34
GOJO Industries
common hand problems encountered by technicians, Jul.30, 32
hand cleaner/brush combo, Sep.78
Gold Eagle, All-Season Water Remover, Jun.79
Golf III (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Golf (Volkswagen)
inoperative cruise control (1995), Jul.72
oil overfill caution (latest generation), Dec.52
vibrating/knocking shift lever (1999), Sep.73-74
GOOP
GOOP Cream, comparison, Jul.34
GOOP Cream with pumice, comparison, Jul.34
GOOP Orange Liquid with pumice, comparison, Jul.34
Grand Am (Pontiac)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
Grand Cherokee (Jeep)
3.9-liter, ignition crossfire (1994-98), Feb.71-72
4.7-liter, new 45RFE transmission explained, Jun.35-38
5.2-liter
detonation complaints (1992-2000), Oct.6, 8
DTC P1494 and/or MIL on (1997-98), Apr.61
ignition crossfire (1994-98), Feb.71-72
5.9-liter
detonation complaints (1992-2000), Oct.6, 8
DTC P1494 and/or MIL on (1997-98), Apr.61
ignition crossfire (1994-98), Feb.71-72
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
horn service (1997-98), Jul.68
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1993-98), Mar.84-85, Oct.26
Grand Marquis (Mercury)
4.6-liter, no crank (1992-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
stall during acceleration and/or turning (1996), Jun.65-66
transmission DTCs stored in memory (1997), May.76
Grand Prix (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
wipers don't park correctly (1997-98), Jun.69
Grand Wagoneer (Jeep), transfer case shifter noise (1993-98), Mar.84-85,

Oct.26
Graphing Multimeters: The Ultimate Time Machine, diagnosing intermittents with a graphing multimeter, Sep.42-47
Gray Automotive
FSJ-40 floor jack, Jun.76
jack and lifting equipment catalog, Apr.66
GreatMechanics.com, partners with Automotive Service Association (ASA), Apr.66
GS 300 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22° F (1993-96), Dec.56
GTI (Volkswagen), inoperative cruise control (1995), Jul.72
Guerrilla Diagnostics
Advanced Honda PCM-FI/OBDII diagnostics training, Oct.30
contact information, Oct.30

H

H1 (Hummer), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76
H2 (Hummer), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76
Hand cleaners
comparison
Gent-L-Kleen
Orange Hand Cleaner, Jul.34
Zapper Paint & Resin Remover, Jul.34
GOJO Hand Care System
Fast Wipes, Jul.34
Hand Medic, Jul.34
Hand Pro, Jul.34
Paint & Stain Remover, Jul.34
Power Gold, Jul.34
Supro, Jul.34
GOOP
GOOP Cream, Jul.34
GOOP Cream with pumice, Jul.34
GOOP Orange Liquid with pumice, Jul.34
Permatex
Fast Orange Cream with pumice, Jul.34
Fast Orange Lotion, Jul.34
Paint & Resin Remover, Jul.34
Stockhausen Hand Care System
Kresto EF Hand Cleaner, Jul.34
Stockolan, Jul.34
Travabon, Jul.34
types, Jul.32
using hand cleaners correctly, Jul.28-30, 32-36
Hannay Reels
hose reel catalog, Mar.89, Dec.64
reference guide, Oct.31
Heaters see under HVAC systems
Hennessey Industries
Ammco Model 1450 Deluxe Brake Washer, Feb.74
Internet e-zine Shop Smarts, Sep.77
Highlander (Toyota), unveiled at New York Auto Show, Jun.51
Hole in the Head, troubleshooting/servicing aluminum cylinder head leaks, Aug.36-40
Honda
see also specific models
diagnosing a bad fast-idle valve, Apr.12, 15
idle speed control system problems, Jun.16, 18
joins California Fuel Cell Partnership, Jan.56-57
new tricks for pulling codes from diagnostic connector, Jun.18
teams up with OnStar/XM Satellite Radio to offer mobile communication services, Jul.62-63
Honeywell Friction Materials, expanded RoadTuff brake products line, Aug.62
Honeywell Consumer Products Group, Genetron 134aUV refrigerant/dye combo, Apr.68
Hot Shot Diagnosis, using infrared thermometers, Mar.22-26
Hotlines see under Contact information
Hotsy, Model 555 hot-water pressure washer, Jul.75
How to be a Media-Savvy Shop Owner, Aug.46-50
Hunter Engineering
OCL360 on-car brake lathe, Mar.91
RL Alignment Lift Rack brochure, Jul.74
Virtual View Alignment Software, Sep.32, 34
website address, Mar.89
HVAC systems
see also A/C systems; Cooling systems
diagnostics using infrared thermometers, Mar.25
electronic climate control (ECC) system
air bag warning, Apr.38
diagnosing, Apr.36-38
replacing, Apr.38
types, Apr.33-34, 36
heaters, Aug.27
pros and cons of shotgunning method of troubleshooting, Apr.28
Quest (Nissan), rear blower doesn't work (1993), Apr.28
retrofit recommendations, Apr.25-26, 28
Villager (Mercury), rear blower doesn't work (1993), Apr.28
Hybrid electric vehicles (HEV)
see also Electric vehicles
2000 North American International Auto Show
Insight (Honda), Mar.79-80
Precept (General Motors), Mar.79
Prius (Toyota), priced, Jul.65
Prodigy (Ford), Mar.77
Escape (Ford), 2003 debut, May.67
Hydro-Blast, aqueous conveyor washer CD, Dec.64
Hyundai
see also specific models
Internet-based service center, Apr.53

I

i2 Technologies, Internet B2B e-commerce alliance formed with Toyota, Apr.50
I30 (Infiniti)
2001 Import Tech Roundup, Dec.34
no start, MIL on, electrical glitches (1996-99), Dec.52
rear brake groan/hum (1996-99), Oct.28
IAMC see International Automotive Media Conference (IAMC)
IBOC DAB see In-Band, On Channel, Digital Audio Broadcasting (IBOC DAB)
iCARumba
automotive service industry website, Feb.64-66
INSITE free website and hosting package, Nov.80
IHRA see International Hot Rod Association (IHRA)
IMACA see International Mobile Air Conditioning Association (IMACA)
Imperial (Chrysler), intermittent cruise control (1990-93), Oct.28
In-Band, On Channel, Digital Audio Broadcasting (IBOC DAB), stereo systems, Jan.29
Infrared thermometers, for diagnostics, Mar.22-26, Jun.6
Insight (Honda)
hybrid electric vehicle (HEV), unveiled at 2000 North American International Auto Show, Mar.79-80
introduced, Jan.57
Intake air system, diagnostics with infrared thermometers, Mar.26
Integra (Acura)
hard to shift five speed (1994-96), Oct.28
rear-end squeak (1990 newer), Apr.61, 63
International Automotive Media Conference (IAMC), MOTOR Magazine receives awards, Jan.56
International Hot Rod Association (IHRA) CARQUEST Auto Parts, Sponsor of the Year, Mar.89
Crown Entertainment Racing Team 1956 Ford Crown Victoria funny car, Mar.28-30
International Lubricants, OE Scheduled Maintenance Handbook Tech Tips/Testimonials section added to website, Dec.64
International Mobile Air Conditioning Association (IMACA), joins National Automotive Radiator Service Association (NARSA), Nov.71
Internet
see also Computers; Software
and the automotive industry, May.2
B2B e-commerce alliances formed, Apr.49-50
Ford, voice-activated Telematics systems, Mar.76
increasing e-commerce, Dec.4
Mercedes-Benz, COMAND offers Internet information, Jan.54, Dec.62
Neighbor (TH!NK) electric vehicle, available for purchase on Internet, Mar.78
stereo systems, S-band technology, Jan.28-29
Uniform Inspection & Communication Guidelines (UICG) Internet-based training program, Sep.77
Intrepid (Dodge)
a/c leak (1995-97), Nov.79
2.7-liter, noisy tensioner (1998), Nov.78
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
new transmission software (1996-97), Apr.59-60
intermittent cruise control (1993-97), Oct.28
NASCAR race car, unveiled at 2000 North American International Auto Show, Mar.81
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Intrigue (Oldsmobile)
3.5-liter, bellhousing bolt precaution (1999), Apr.54
wipers don't park correctly (1998), Jun.69
IS 300 (Lexus)
2001 Import Tech Roundup, Dec.28
2001 model introduced, Aug.56-57
iStarXchange, Internet B2B e-commerce alliance formed by Toyota and i2 Technologies, Apr.50
Isuzu
see also specific models
revised water pump procedure, Dec.48
It Turns Out Image Is Everything, fighting negative image of automotive aftermarket industry, Jun.40-43
ITE see SEMA Show-International Tire Expo (ITE)

J

J-car (General Motors), ABS light on (1992-97), Dec.56
Jaguar
see also specific models
pressure switch replacement (prior to 1992), Jan.63
Jazz Designs
AUTOS2000 Automotive Shop Management new software features, Jul.74
contact information, Jul.74
Jendham, GM ABS clinic, Apr.66
Jetta (Volkswagen)
2.8-liter, rough idle, poor performance (1992-94), Mar.85
inoperative cruise control (1995), Jul.72
oil overfill caution (latest generation), Dec.52
vibrating/knocking shift lever (1999), Sep.73-74
Jetta GLX (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Jetta III (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Jimmy (GMC), inoperative heated front passenger seat (1998), Aug.59
Junkyard Wars, team search, Jun.75

K

K&W Acquisition Group, acquired by CRC Industries, Jan.64
K1500 (GMC), delayed or no front axle engagement (1988-97), Apr.60-61
K2500 (GMC)
delayed or no front axle engagement (1988-97), Apr.60-61
rear wheel lockup and slight pull (1990), Mar.6-7
K3500 (GMC), delayed or no front axle engagement (1994-97), Apr.60-61
Kaeser Compressors, Designing Your Compressed Air System, Mar.89
Kastar Hand Tools, Torx ratcheting box wrench set, Jan.65
Ken-Tool, Bead-Eze tire lubricant, Mar.91
Kent-Moore
ACR 2000 A/C Service Center, Apr.28, 30, 68, Sep.36-37
Saab, special ignition tool, Jan.61
Kolbenschmidt Pierburg, smart secondary air blower, May.67-68

L

L-car (General Motors), ABS light on (1991-96), Dec.56
Lab scopes
Assessment quiz, May.55-56
Mastering the Basics, May.51-54
LaCrosse (Buick), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76-77
Land Cruiser (Toyota)
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
Lease2save.com, Inc., lease proposal website, May.79
LeBaron (Chrysler)
3-liter, harsh shifting (1992-95), Feb.69
front power window won't go up (1994-95), May.77
intermittent cruise control (1989-95), Oct.28
LeBaron Convertible (Chrysler)
intermittent cruise control (1990-95), Oct.28
PCM reflashing tips (1995), Dec.50
LeBaron Coupe (Chrysler), intermittent cruise control (1990-95), Oct.28
Lenan
Lanair Recyclit Model SR80 XP solvent recycler, Jan.65
SR8ss waste solvent recycler, May.81
LeSabre (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Lexus
see also specific models
a/c compressor damage in stored vehicles, Oct.26-27
Leybold Inficorn, TEK-Mate, refrigerant leak detector, Apr.68
LHS (Chrysler)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Lincoln
see also specific models
complimentary maintenance, Jun.58
Lincoln Electric, free wall chart, Oct.31
Linder Technical Services, reman central port injection assemblies for GM, Jul.75
Lisle, Spill-Free Coolant Funnel, Sep.31
LKQ Corp., free parts replacement guarantee, Mar.89
LS 400 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
more durable blower motor (1998-99), Nov.79
outside temperature reads -22o F (1993-96), Dec.56
LS 430 (Lexus), 2001 Import Tech

2000 Motor Magazine Index

Roundup, Dec.26, 28
LS (Lincoln)
checking the heating system, Aug.27
filling the cooling system, Aug.25-26
LSS (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Lube, oil & filter change (LOF)
OE Scheduled Maintenance Handbook Tech Tips
chassis lubrication, Feb.49
oil change, Feb.47, 49
oil filter change, Feb.49
Lubrimatic, grease gun brochure, Jun.75
Lumina APV (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
Lumina (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, power steering shudder (1998-99), Mar.85-86
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
LX 470 (Lexus), more durable blower motor (1998-99), Nov.79

M

M/L-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
M3 (BMW), 3.2-liter, proper thermostat replacement (1998 newer), Dec.50
Mac Tools, Flex Head Indexable Ratchet, Sep.32
MACS see Mobile Air Conditioning Society (MACS)
Malibu (Chevrolet)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.4-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1997), Feb.69
MAP see Motorist Assurance Program (MAP)
Mark VIII (Lincoln)
blower motor squeak/chirp (1993-97), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1993-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1996-98), Feb.72
transmission DTCs stored in memory (1997), May.76
Maserati TC (Chrysler), intermittent cruise control (1990-91), Oct.28
Mastercool, A/C Valve Core Remover/Reinstaller Kit, Sep.30-31
Mastering the Basics
assessment quiz
electrical systems, Nov.39-40
engine performance, Aug.29-32
lab scope, May.55-56
steering and suspension, Mar.67-68
assessment quiz answers
ABS system, Mar.70
August, 2000 engine performance, Nov.38
March, 2000 steering and suspension, May.54
May, 2000 lab scope, Aug.32
electronic fuel injection, Aug.29-32
lab scopes, May.51-54
steering & suspension, Mar.65-70
troubleshooting electrical accessories, Nov.35-38
Matco Tools
combo fuel injector/EGR tester, Sep.80
Determinator Series ABS testers, Jun.76
Special Forces 3/8-inch Air Ratchet, Sep.35-36, Oct.35
Maxima (Nissan)
2001 Import Tech Roundup, Dec.34
a/c switch sticks on or off (1996-98), Apr.28
no heat after cooling system flush (late 80s-early 90s), Feb.4-5
MAXXcab (Dodge), concept vehicle unveiled at 2000 North American International Auto Show, Mar.75
McQuay-Norris, chassis component catalog, Nov.80
MDX (Acura), 2001 Import Tech Roundup, Dec.30-32
MechanicNet.com, strategic alliance with ALLDATA, Jul.61
MEMA see Motor & Equipment Manufacturers Association (MEMA)
Mercedes-Benz
see also specific models
automatic transmission fluid caution (1997 newer), Apr.64
COMAND offers Internet information, Dec.62
Flexible Service System, Feb.63
intelligent car technologies, Jan.54, 56
Mercedes-Benz Client Assistance Center, access from car, Jan.54, 56
MG Generon, NITRO-FILL tire-inflation system, Feb.63-64
Mighty Auto Parts, Engine Guard II oil filters, Aug.66
Millenia (Mazda)
MIL on with DTCs P0300 through P0306 (1997-98), Sep.70
piston standardization (1995-99), Nov.77-78
Miller Electric Mfg., welding and plasma cutting product catalog, Mar.89
Mini Cooper (BMW)
2002 model unveiled, Nov.68-69
launched worldwide, Apr.51
Minivan (Chrysler), 2001 Domestic Tech Preview, Nov.28, 30
Mirage (Mitsubishi), coolant service (1993-96), Jan.63
Misfire monitors, diagnostics, May.27-30, 32, 36
Mitsubishi
see also specific models
2000 Light Truck Service Report
Tomco replacement aftermarket choke pinion gear, Jun.76
ML320 (Mercedes-Benz), low range light on (1998), Feb.69
M.M. Newman, Antex MLXS portable soldering iron, Sep.78
Mobil 1
motor oil survey results, Jan.57
pros and cons of synthetic oil, Feb.6, 86
Mobile Air Conditioning Society (MACS)
a/c survey results, Mar.4
2000 A/C Report, Apr.22-26, 28, 30
retrofit business growing, Apr.25-26
Society of Automotive Engineers (SAE) Performance Review Institute, rating system and certification program, Apr.23
website address, Mar.4
Modine
AirPro Quality Parts catalog, Jul.74
Lifetime Protection Free! poster & counter card, Nov.80
Mohawk Resources Ltd., HR-6 portable midrise lift, Dec.65
Monte Carlo (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, power steering shudder (1998-99), Mar.85-86
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Montero (Mitsubishi)
3-liter, engine bearing ID (1996-96), Nov.79
coolant service (1992-96), Jan.63
Montero Sport (Mitsubishi), 2000 Light Truck Service Report, Jan.42
Mopar Parts, longer warranty on remanufactured powertrain components, Sep.77
Motor & Equipment Manufacturers Association (MEMA)
1999 Automotive Industry Status Report, May.69
Automotive Aftermarket Industry Week (AAIW), Sep.77
automotive maintenance spending report, Feb.67
Global Automotive Aftermarket Symposium (GAAS), Jun.2
MOTOR Magazine
10th International Automotive Media Conference (IAMC) awards received, Dec.62
2000 ASE Master Automobile Technician of the Year, Dec.58
Crash Estimating Guides online, Jan.53
hand-care study, Jul.33-34, 36
honors Bob Cerullo, Dec.62
International Automotive Media Conference (IAMC) awards received, Jan.56
Labor Guides online, Jan.53
lawsuit against W.G. Nichols, Inc., Jan.2, 4
Parts & Time Guides online, Jan.53
Source Guide 2000 on-line, Jan.52-53
Motorist Assurance Program (MAP)
contact information, Jun.42
fighting negative image of automotive aftermarket industry, Jun.42
media reaction to Uniform Inspection and Communication Guidelines, Aug.47
Uniform Inspection & Communication Guidelines (UICG) Internet-based training program, Sep.77
Motorvac Technologies
CoolantClean automated cooling system service machine, Oct.35
MV4 Air Intake & Throttle Body Cleaner, May.79
Mountaineer (Mercury)
4-liter, hesitation, harsh downshift (1997-99), Jan.62-63
5-liter, hesitation, harsh downshift (1997-99), Jan.62-63
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, DTCs, O2 sensor leak (1997-98), Dec.56
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1997-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
MR2 (Toyota)
2001 Import Tech Roundup, Dec.28-29
steering gear service precaution (1996 newer), Dec.50
surging idle (1987-91), Jan.20, 22
Mustang (Ford)
3.8-liter, PCM reprogramming flash cable available (1994-99), Feb.72
4.6-liter, PCM reprogramming flash cable available (1996-99), Feb.72
5-liter, won't shift into any gear with motor running (1987), Jul.10, 12-13
blower motor squeak/chirp (1994-97), Aug.58, Nov.78
clutch vibration (1991-98), Nov.76
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
transmission DTCs stored in memory (1998), May.76
MX-5 Miata (Mazda), MIL on, DTC P0300 (1997), Jul.70
MX-6 (Mazda), dead power driver's seat (1993-94), Jan.63
Mystique (Mercury)
2.5-liter, MIL on, DTCs stored (1996-98), Jul.72-73
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-99), Feb.72

N

N-car (General Motors), ABS light on (1991-96), Dec.56
NAPA/ASE Technician of the Year, Feb.63, Dec.64
NAPA Chassis, vehicle alignment and chassis components promotion, Jan.64
NAPA Hand Tools, new screwdriver set, Sep.79
NAPA Institute of Automotive Technology (N.I.A.T.)
contact information, Aug.62
earns Continuing Automotive Service Education (CASE) certification, Aug.62
NAPA Rayloc, helps fund scholarship program, Nov.80
NAPA/United, Moisture Alert Brake Fluid Test Strips, Sep.78-79
NAPA United, power brake booster catalog, Dec.64
NARSA see National Automotive Radiator Service Association (NARSA)
NASCAR
Intrepid (Dodge), race car unveiled at 2000 North American International Auto Show, Mar.81
NASCAR. Your Car promotion, Jan.64
WIX Filtration Products, racing contract extensions, Apr.66
NATEF see National Automotive Technicians Education Foundation (NATEF)
National Automotive Radiator Service Association (NARSA)
cooling tips, Aug.22-27
joins International Mobile Air Conditioning Association (IMACA), Nov.71
National Automotive Technicians Education Foundation (NATEF), Continuing Automotive Service Education (CASE) certification to N.I.A.T, Aug.62
National Highway Safety Administration (NHTSA), battle with BMW over VIN code changes, Jan.57
National Highway Traffic Safety Administration (NHTSA), US fuel economy report, Nov.69-70
National Hot Rod Association (NHRA)
Federal-Mogul awards to NHRA Sportsman competitors, Mar.89
continued support for NHRA drag racing, Aug.62
WIX Filtration Products, racing contract extensions, Apr.66
National Institute for Automotive Service Excellence (ASE)
Bergwall Productions, test prep guides, Jun.76
contact information, Jun.42
fighting negative image of automotive aftermarket industry, Jun.42-43
Glove Box Tips brochure series, Jun.42
Navajo (Mazda), rattling exhaust (1991-94), Oct.26
Navigator (Lincoln)
2000 Light Truck Service Report, Jan.40-41
5.4-liter, high fast idle with MIL illuminated and DTC stored (1998), Apr.57
ABS light on (1998-99), Oct.24
air suspension iight on (1997-99), Jun.69
binding ignition key (1998-99), Nov.75
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1998-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
Neighbor (TH!NK), electric vehicle available through Internet, Mar.78
Neon (Dodge/Plymouth)
2-liter
misfire DTCs with no symptoms (1997-99), May.70
shaking and check engine light on (1997), Feb.10, 11-12
bouncing tach (1997-98), Jul.68
cam sensor oil leak (1995-99), Jan.60-61
cooling fan quits or won't stop running

(1997-98), Oct.24
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
New Beetle (Volkswagen)
new alignment specs (1998 on), Nov.79
oil overfill caution (latest generation), Dec.52
unnecessary body computer replacement (1998 and newer), Apr.60
New Yorker (Chrysler)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1989-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
New Yorker Fifth Avenue (Chrysler), intermittent cruise control (1990-93), Oct.28
New Yorker Salon (Chrysler), intermittent cruise control (1989-93), Oct.28
Newsbreak
10th International Automotive Media Conference (IAMC) Awards, Dec.62
2000 Ford/AAA Student Auto Skills national finals winners, Aug.55
2000 MOTOR Magazine ASE Master Automobile Technician of the Year, Dec.58
2000 North American International Auto Show report, Mar.75-81
aftermarket wins OBDII information battle, Nov.68
ALLDATA, strategic alliance with MechanicNet.com, Jul.61
Around the World in 80 Days Motor Challenge, Aug.55-56
Automotive Aftermarket Industry Association (AAIA), Aftermarket Factbook, Sep.66
Automotive Service Association (ASA)
2000 annual meeting, Jun.53-54
Arizona affiliate rejoins, Jan.56
partners with Department of Environmental Quality (DEQ), Feb.63
shop licensing report, Jul.62
Automotive Service Association of Oregon, pursues shop licensing, Sep.64
AUTOVIA, connecting repair shops with suppliers via the Internet, Jun.54, 56
B2B Internet e-commerce alliances formed, Apr.49-50
BMW, National Highway Safety Administration (NHTSA), battle over VIN code changes, Jan.57
BMW Group, new Mini launched worldwide, Apr.51
California Air Resources Board (CARB), electric vehicle study results, Jul.61
Chrysler unveils 2001 Sebring, Jul.61
Clevite Engine Parts, new piston ring design, Jan.56
Covisint, automotive Internet exchange named, Jun.56, 58
DaimlerChrysler Corp.
Freightliner Division purchases Western Star, Sep.64
leaves Global Climate Coalition (GCC), Apr.53
product liability lawsuit dismissed, Jun.59
domestic car number survey results, Apr.53
Environmental Protection Agency (EPA)
diesel emissions linked to cancer, Feb.67
disposable refrigerant cylinder debate, Aug.55
fuel economy report, Jan.57
new SUV & truck emissions standards, Feb.66-67, May.68-69
environmentalists protest dropping Florida emissions tests, Jul.63, 65
Escape (Ford), hybrid-electric vehicle (HEV), 2003 debut, May.67
Federal-Mogul, two new Technical Education Centers, May.69
Florida considers elimination of emission inspections, Apr.53
Ford
joins Qualcomm to create Wingcast wireless mobility and information services, Sep.66-67
readies for 42-volt systems, Jun.51-52
Worldwide Diagnostic System (WDS) ahead of schedule, Apr.51, 53
General Motors
hybrid powertrain in full-size truck, Sep.64, 66
team with BP on low-sulfur gasoline, Dec.60-62
General Motors Performance Parts, Ram Jet 350 small block engine, Jul.61-62
Highlander (Toyota), unveiled at New York Auto Show, Jun.51
Honda joins California Fuel Cell Partnership, Jan.56-57
Honda/OnStar/XM Satellite Radio team up to offer mobile communication services, Jul.62-63
Hyundai, Internet-based service center, Apr.53
iCARumba, automotive service industry website, Feb.64-66
improving fuel economy of governmental vehicle fleet, Jun.56
Insight (Honda), introduced, Jan.57
intelligent car technologies, Jan.54, 56
International Mobile Air Conditioning Association (IMACA), joins National Automotive Radiator Service Association (NARSA), Nov.71
IS 300 (Lexus), 2001 model introduced, Aug.56-57
Kolbenschmidt Pierburg, smart secondary air blower, May.67-68
Lincoln, complimentary maintenance, Jun.58
MechanicNet.com, strategic alliance with ALLDATA, Jul.61
Mercedes-Benz
COMAND offers Internet information, Dec.62
Flexible Service System, Feb.63
MG Generon, NITRO-FILL tire-inflation system, Feb.63-64
Mini Cooper (BMW), 2002 model unveiled, Nov.68-69
Mobil 1, motor oil survey results, Jan.57
Motor & Equipment Manufacturers Association (MEMA)
1999 Automotive Industry Status Report, May.69
automotive maintenance spending report, Feb.67
MOTOR Magazine
honors Bob Cerullo, Dec.62
International Automotive Media Conference (IAMC) awards received, Jan.56
NAPA/ASE Technician of the Year, Feb.63
National Automotive Radiator Service Association (NARSA), joins International Mobile Air Conditioning Association (IMACA), Nov.71
National Highway Traffic Safety Administration (NHTSA), US fuel economy report, Nov.69-70
Prius (Toyota), hybrid electric vehicle (HEV), priced, Jul.65
random antifreeze inspections in Florida, May.68
RAV4 (Toyota), unveiled at New York Auto Show, Jun.51
Saab
Saab Combustion Control (SCC) System, Dec.58-60
SVC concept engine, Apr.50-51
Saturn, offers front and rear curtain airbags, Sep.64
Service Technicians Society (STS)
2000 World Congress, Apr.49
OBDII training video, Jun.52-53
Society of Automotive Engineers (SAE), 2000 World Congress, Apr.49
SPX Service Solutions, use of NASA technology for emission monitoring remote sensor, Sep.66
SUV (Saturn), 2002 model unveiled, Nov.68
Tempo (Ford), blower motor squeak/chirp (1984-94), Aug.58, Nov.78
Texas Natural Resource Conservation Commission (TNRCC), vehicle scrappage program proposed, May.68
U.S. Senate
Commerce Committee targets defective vehicle parts, Nov.71
debates ethanol, Aug.57
NHRA see National Hot Rod Association (NHRA)
NHTSA see National Highway Safety Administration (NHTSA)
N.I.A.T see NAPA Institute of Automotive Technology (N.I.A.T)
Nickson Industries, exhaust gasket catalog and application guide, Aug.62
Ninety Nine (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Ninety Nine Regency (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Nissan
see also specific models
2000 Light Truck Service Report, Jan.41
Covisint, automotive Internet exchange, Jun.56, 58
cranks but won't start troubleshooting procedure, Oct.27-28
Nylok Fastener, new NYTEMP brochure, Apr.66

O

OBDII
aftermarket wins information battle, Nov.68
California legislation closer to passing, Aug.2
Honda, new tricks for pulling codes from diagnostic connectors, Jun.18
investigating the Misfire Monitor, May.27-30, 32, 36
Scan Data: How Much is Too Much?, May.40-42, 44, 46-47
Odyssey (Honda), O2 sensor tests (2000), Oct.20, 22
OE Scheduled Maintenance Handbook
CV Joint Diagnosis chart, Feb.37
importance of a scheduled maintenance program, Feb.28-29
leased vehicle indifference, Feb.29
Tech Tips
brake systems, Feb.31, 33
cooling systems, Feb.35
drivelines, Feb.36-37
engine performance, Feb.39, 41-45
exhaust systems, Feb.34
lube, oil & filter change (LOF), Feb.47, 49
safety & convenience items, Feb.51
steering & suspension systems, Feb.52-53
Oils
see also Synthetic oils
contaminants, Jan.44-45
Orion Safety Products, first aid kits, Mar.91
Osram Sylvania, Automotive Lamp Replacement Guide on website, Oct.30
OTC
Fuel Injection Service Kit, Jan.65
Genisys Information System, Sep.32
Model 1727 2-ton service jack, Jul.75
Smart Funnel, Sep.80
Under-Hoist Stand, Jun.78
Outback Wagon H-6 (Subaru), 2001 Import Tech Roundup, Dec.34
O2 sensors see under Sensors
Ozone Protection Hotline, Mar.4

P

P-body truck (Chevrolet/GMC)
4.3-liter, EGR valve recall (1996-97), Mar.82-83
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
PageViews, marketing website, Nov.80
Park Avenue (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter
excessive oil consumption, tests ok, Sep.6, 8
revised dipstick tube and dipstick, Sep.6, 8
3100/3400/3800, hard-start/no-start (1996), Jan.62
brake noise (1997-98), Jul.68
failed emissions test (1994), Nov.12-13
intermittent Neutral on the highway (1995-96), Sep.73
Parts, accessories and supplies
see also Tools and equipment; Tools of the Trade; Top 20 Tools
MOTOR Magazine hand care study, Jul.33-34, 36
new alternator designs, May.22, 24-25
Uview Ultraviolet Systems, AirLift cooling system air remover, Aug.26-27
Parts Plus, 2000 Parts Plus Guide to NASCAR, May.79
Paseo (Toyota)
steering gear service precaution (1996 newer), Dec.50
surging idle (1990-94), Jan.20, 22
Passat (Volkswagen)
2.8-liter, rough idle, poor performance (1992-94), Mar.85
oil overfill caution (latest generation), Dec.52
unnecessary body computer replacement (1998 and newer), Apr.60
vibrating/knocking shift lever (1997), Sep.73-74
Passat GLX (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Pennzoil-Quaker State, synthetic motor oil, Nov.81
Permatex
Fast Orange Cream with pumice, comparison, Jul.34
Fast Orange Lotion, comparison, Jul.34
Paint & Resin Remover, comparison, Jul.34
Phoenix Systems, brake fluid test strips, Mar.91
Pickup (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
Popular Mechanics, Tools for Schools program, Oct.30
Precept (General Motors)
fuel cell vehicle, unveiled at 2000 North American International Auto Show, Mar.79
hybrid electric vehicle (HEV), unveiled at 2000 North American International Auto Show, Mar.79
Prelude (Honda)
clunking from power windows (1997-98), Jul.71
cracking rubber in harmonic balancer (1988-91), Aug.14, 17
Prestolite Wire, acquired Speed Clip Division of Exide Corp., Feb.73
Previa (Toyota)
improved rear a/c magnetic valve (1991-97), Apr.55
steering gear service precaution (1996 newer), Dec.50
surging at cruise (1991-92), Jan.22
Prism Enterprises
Mityvac Fluid Evacuator, May.81
Mityvac Heater & Evaporator Core Test Accessories Kit, Sep.79
Prius (Toyota), hybrid electric vehicle (HEV) priced, Jul.65
Pro-Cut International
Discus Rotor Measuring System, Sep.28
free used brake lathes for tech schools, Apr.66
Probe (Ford), 2-liter, PCM reprogramming flash cable available (1996-97), Feb.72
Probing the Mysteries of ABS, diagnostics with a current probe and scope, Jun.26-28, 30-31
Prodigy (Ford), hybrid electric vehicle (HEV), unveiled at 2000 North American International Auto Show, Mar.77
Prowler (Plymouth)
3.5-liter, fuel system recall (1997), Mar.83

2000 Motor Magazine Index

cold-start sputtering (1997), Sep.73
PCM reflashing tips (1997-99), Dec.50
PT Cruiser (Plymouth)
2001 Domestic Tech Preview, Nov.28
unveiled at 2000 North American International Auto Show, Mar.81
Purolator Products, PureONE oil filters, Oct.36

Q

Quest (Nissan), rear blower doesn't work (1993), Apr.28

R

Racing
2000 TV Race Schedule, Mar.33-40
Crown Entertainment Racing Team, 1956 Ford Crown Victoria IHRA funny car, Mar.28-30
Why They Race, Mar.43-64
WIX Filtration Products, NASCAR and NHRA racing contract extensions, Apr.66
Radiators see under Cooling systems
Radios see Stereo systems
Ram (Dodge)
3.9-liter, ignition crossfire (1994-99), Feb.71-72
5.2-liter, ignition crossfire (1994-99), Feb.71-72
5.9-liter, ignition crossfire (1994-99), Feb.71-72
clunk/rattle in steering column (1994-95), Mar.85
injection pump tampering (1994-97), Jan.58
sluggish acceleration, false MIL (1998-99), May.73-74
steering column noise (1994-97), Apr.54
Ram pickup (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1995-96), Dec.56
asbestos brakes (1997-99), Jun.74
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
squeak from rear leaf springs (1994-99), Sep.68
Ram Van (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1992-96), Dec.56
asbestos brakes (1995-97), Jun.74
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
front end clunk (1995-97), Feb.70
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
squeak from rear leaf springs (1994-99), Sep.68
Ram Wagon (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1992-96), Dec.56
asbestos brakes (1995-97), Jun.74
false MIL with various DTCs (1997), Nov.79
front end clunk (1995-97), Feb.70
no crank (1994-97), Sep.76
sluggish acceleration, false MIL (1998-99), May.73-74
squeak from rear leaf springs (1994-99), Sep.68
Range Rover (Land Rover)
3.9-liter, wrong ignition timing (1994), Apr.56
leaking transfer case output seals (prior to 1998), Apr.63
Range Rover Classic (Land Rover)
3.9-liter
camshaft knock (1995), Jan.61-62
hard start in cold weather (1993-95), May.73
4.2-liter, hard start in cold weather (1993-95), May.73
Ranger (Ford)
fuel pump service tip (1998), Sep.70, 72
high idle during closed-throttle decel (1998-99), Jul.73
PCM reprogramming flash cable available (1995-99), Feb.72
power window drops only 5 inches (1998), Nov.79
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
RAV4 (Toyota)
2001 Import Tech Roundup, Dec.28-29
unveiled at New York Auto Show, Jun.51
Raybestos Brakes
domestic and import brake parts catalog, Jan.64
Electric Trailer Brake Catalog, Jun.75
loaded calipers carry D3EA certification, Feb.73
new Quiet Stop products added, Oct.31
Super Stop Severe Duty Rotors, Aug.66
Synthetic Moly Paste high-temperature brake lubricant, Mar.91
updated Brake and Safety Center program, Apr.66
website address, Apr.66
RCRA see Resource Conservation and Recovery Act (RCRA)
Refrigerants
see also A/C Systems
disposable refrigerant cylinder debate, Aug.55
DuPont Suva, 134a wins award, May.79
retrofit business growing, Apr.25-26
Regal (Buick)
3.1-liter, premature cranking with new PCM (1997), Apr.58
3.8-liter, premature cranking with new PCM (1997), Apr.58
intermittent Neutral on the highway (1995-97), Sep.73
shaking sensation on smooth roads (1997-99), Oct.26
using the shotgun method of troubleshooting the a/c system (1999), Apr.28
wipers don't park correctly (1997-98), Jun.69
Rema Tip Top/North America
Angle-Head Tire Buffers, Nov.81
Rep Boy Tire Inspection & Repair Station, Oct.35
Renault, Covisint, automotive Internet exchange, Jun.56, 58
Resource Conservation and Recovery Act (RCRA), hotline, Jan.45
Riviera (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
brake noise (1997-98), Jul.68
intermittent Neutral on the highway (1995-96), Sep.73
Roadmaster (Buick), engine miss, poor driveability (1994-96), Jun.63
Robinair
CoolTech 134 compact a/c station, Sep.78
Engine Oil Service Solutions engine cleaning machine, May.81
Enviro-Charge Dual, a/c station, Jun.78
updated website, Feb.73
Rodeo (Isuzu)
3.2-liter
updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
valvetrain tick (1997 and earlier), Dec.57
inoperative speedometer (1991-96), Jun.62
rear axle leaks (1998-99), Aug.58-59
Rotary Lift
75th anniversary celebration, Mar.89
automotive lift brochure, Jun.75
Inground Lift Replacement Program, May.79
The Lift Buyer's Bible, Jan.64
website address, Jan.64, Mar.89, Aug.62
Rotor Clip, retaining ring pliers, Apr.68
RTI Technologies, Midas preferred supplier, Mar.89
Run-Rite, Intake Snake, Sep.27-28
RVA4 (Toyota), steering gear service precaution (1996 newer), Dec.50
RX 300 (Lexus)
false DTC P0446 (1999), Apr.64
front brake squeal (1999), Jul.73

S

S-band technology, stereo systems, Internet access, Jan.28-29
S-Class (Mercedes-Benz)
2001 Import Tech Roundup, Dec.32
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
automatic transmission fluid caution (1996), Apr.64
no crank, blown cigarette lighter fuse (1994-95), Apr.56
S/T-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
dead battery, alternator not charging (1998), Jun.74
horn blaring or fuel pump runs continuously after heavy rain or car wash (1998), Oct.28
S70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
S90 (Volvo), revised power steering parts (1997), Nov.78
Saab
see also specific models
Combustion Control (SCC) System, Dec.58-60
Saab Combustion Control (SCC) System, Dec.58-60
special ignition tool, Jan.61
SVC concept engine, Apr.50-51
Sable (Mercury)
3-liter
automatic transmission identification (1994-96), Mar.83
hesitation, delayed downshift (1996-97), Jun.63
ABS noise (1998-99), Jun.74
automatic transmission identification (1986 on), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Moog Automotive, improved non-greasable front stabilizer bar link (1986-95), Jun.66, 68
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
popping noise in front end (1986-95), Jan.60
rear tire wear (1996-97), May.78
transmission DTCs stored in memory (1998), May.76
Safari (GMC), climate control knobs spin (1996-97), Jul.73
Safe Shop Tools, safe tool catalog, Apr.66
Safety
common hand problems encountered by technicians, Jul.30, 32
minimizing the effects of electrostatic discharge (ESD), Jul.16-18
OE Scheduled Maintenance Handbook Tech Tips, safety & convenience items, Feb.51
on-board computer software adds greater safety features to new vehicles, Sep.22, 24
using dynamometers, Nov.47
using hand cleaners correctly, Jul.28-30, 32-34, 36
Safety-Kleen
AquaWorks-The Power of Water brochure, Jul.74
CabPak chemical management, storage, packaging and disposal program, Mar.89
Compliance Solutions: Compliance You Need...When You Need It, May.79
contact information, Jan.46
We Care environmental education program, Jan.45-46
Saturn
2001 Domestic Tech Preview, Nov.26-27
intermittent no click, no crank, no start (1998), Oct.26
offers front and rear curtain airbags, Sep.64
transaxle valve body cover gasket service (1991-96), Sep.70
Savanna (GMC), 4.3-liter, slower-than-normal downshifts (1997), Jun.66
SC 300 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22o F (1993-96), Dec.56
SC 400 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22o F (1993-96), Dec.56
Scan tools
diagnosing fuel delivery problems, Feb.14, 16
Scan Data: How Much is Too Much?, May.40-42, 44, 46-47
Scott Specialty Gases
contact information, Oct.30
Design & Safety handbook for Specialty Gas Delivery Systems, Oct.30
Sebring (Chrysler)
2001 Domestic Tech Preview, Nov.30, 32
2.0-liter, new transmission software (1996-97), Apr.59-60
2.5-liter, head gasket running change (1995-2000), Jun.66
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1996-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
Sebring Convertible (Chrysler)
intermittent cruise control (1996-99), Oct.28
PCM reflashing tips (1996-99), Dec.50
Selling Diagnostic Time Profitably, Dec.39-42
SEMA see Specialty Equipment Market Association (SEMA)
SEMA Show-International Tire Expo (ITE), Automotive Aftermarket Industry Week (AAIW), Sep.77
Sensors
crankcase, diagnosing trouble in Toyotas, Feb.21
offer greater safety features on new vehicles, Sep.22, 24
O2 sensors
diagnosing with scan tool, Feb.14, 16
flange gasket leakage, Mar.20-21
OE Scheduled Maintenance Handbook Tech Tips, Feb.41-42
replacement intervals, Nov.20-22
schedule maintenance, Feb.41-42
tests run, Oct.20, 22
using post catalytic sensors for diagnostics, Apr.16, 19, 21
throttle position, Toyota, diagnosing idle speed & surging complaints, Jan.20, 22
Vehicle Speed Sensor (VSS), signal glitches, Feb.18-21
Sequoia (Toyota), 2001 model unveiled at 2000 North American International Auto Show, Mar.79-80
Service Slants
3-series (BMW), air bag light on (1994-99), Jun.68
A4 (Audi)
2.8-liter, engine cranks but won't start (1998-99), Dec.57
delayed 1-2 shift after cold start (1996

2000 Motor Magazine Index

newer), Jun.61
low fuel level warning (1995), Mar.86-87
MIL on, low fuel level (1995), Apr.58
4Runner (Toyota)
buzzing evap canister (1996), Nov.75
cylinder head service (1988-95), Apr.65
snow in HVAC box (1996-98), May.76
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
5-series (BMW), air bag light on (1997-99), Jun.68
A6 (Audi)
2.8-liter, engine cranks but won't start (1998-99), Dec.57
delayed 1-2 shift after cold start (1995 newer), Jun.61
low fuel level warning (1995), Mar.86-87
MIL on, low fuel level (1995), Apr.58
7-series (BMW), air bag light on (1995-99), Jun.68
A8 (Audi), delayed 1-2 shift after cold start (1997 newer), Jun.61
88 Royale (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
90 (Audi), MIL on, various EGR DTCs (1995), Sep.75
98 Regency (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
300M (Chrysler)
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
318 (BMW), 1.8-liter, jolt on acceleration (1994-95), Mar.86
323is (BMW)
2.5-liter, valve timing mechanism jams (1998-99), Apr.57
2.8-liter, valve timing mechanism jams (1998-99), Apr.57
328i (BMW)
2.5-liter, valve timing mechanism jams (1996-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1996-98), Apr.57
328is (BMW)
2.5-liter, valve timing mechanism jams (1996-99), Apr.57
2.8-liter, valve timing mechanism jams (1996-99), Apr.57
525i (BMW), air bag light on (1995-99), Jun.68
528i (BMW)
2.5-liter, valve timing mechanism jams (1997-98), Apr.57
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1997-98), Apr.57
530i (BMW), air bag light on (1995-99), Jun.68
540i (BMW)
4.4-liter, cranks but won't start (1997-99), May.74-75
air bag light on (1995-99), Jun.68
626 (Mazda)
dead power driver's seat (1993-94), Jan.63
MIL on with DTCs P0300 through P0306 (1997), Sep.70
740i (BMW)
4-liter, inoperative oil level sensor (1995), Sep.73
4.4-liter, cranks but won't start (1997-99), May.74-75
740iL (BMW), 4-liter, inoperative oil level sensor (1995), Sep.73
750i (BMW), 4.4-liter, cranks but won't start (1997-99), May.74-75
850 (Volvo)
fuel pulsation damper (1997 newer), Sep.76
new O2 sensor wiring (1996-98), Apr.60
new PCMs (1996-97), Oct.26
new starter motor (after 1997), Jan.61
900 (Saab)
battery drain (1987-89), Jan.63
brake vibration (1994 on), Jun.64
engine compartment noise (1994 newer), May.76
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
911 (Porsche), intake camshaft service (1999 on), May.73
911 Carrera (Porsche)
front end creaking/groaning (1995), Jun.64
vacuum line caution (1995-96), Apr.65
911 Carrera 2 (Porsche), fuel odor (prior to 1994), Jan.63
911 Carrera 4 (Porsche)
fuel odor (prior to 1994), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
911 Carrera Cabriolet (Porsche), convertible top motor service (1996), Dec.56
911 Turbo (Porsche)
front end creaking/groaning (1996), Jun.64
fuel odor (1991-94), Jan.63
slight vibration between 110-125 mph (1995-96), Aug.61
vacuum line caution (1996), Apr.65
960 (Volvo), spring sound from steering wheel (1992-94), Feb.71
2500 (Dodge), accelerated front brake wear (1994-97), Jan.62
2500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
3000GT (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
3500 (Dodge), accelerated front brake wear (1994-97), Jan.62
3500-series (Chevrolet/GMC), rear axle leak (1992-96), Dec.50
9000 (Saab)
engine compartment noise (1994 newer), May.76
speedometer quits working (1996-98), Dec.56
SRS light on, DTC B1605 (1995), Aug.61
sticking power antenna (1992), Apr.56-57
wrong grounding point locations (1993 newer), Apr.64
Accent (Hyundai)
revised TCMs (1996), Nov.75-76
timing chain noise (1997), Jun.68
Acclaim (Plymouth)
3-liter, harsh shifting (1992-95), Feb.69
intermittent cruise control (1989-95), Oct.28
PCM reflashing tips (1995), Dec.50
Accord (Honda)
brake light stays on (1998), Apr.63
steering rack squeak (1990-93), Mar.87
Achieva (Oldsmobile)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
Aerostar (Ford)
blower motor squeak/chirp (1992-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-97), Feb.72
popping/clunking when braking and turning (1991-93), Jul.66
transmission DTCs stored in memory (1997), May.76
whistling/hissing from transmission (1997), Aug.59
AJ16 (Jaguar), waterlogged PCM (1995), May.77
Allante (Cadillac), oil ring installation revision (1993), Aug.61
Altima (Nissan)
MIL on with DTC P0300 (1997-1/2), Jul.72
MIL on with DTCs P0130 and/or P0136 (1997), Sep.70
Amigo (Isuzu), 3.2-liter, updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
Astro (Chevrolet), climate control knobs spin (1996-97), Jul.73
Audi, heated mirror mysteries (1997 on), Jun.70
Aurora (Oldsmobile)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter, updated fuel pressure readings (1998), May.72
brake noise (1997-98), Jul.68
oil ring installation revision (1997), Aug.61
Avalon (Toyota), steering gear service precaution (1996 newer), Dec.50
Avenger (Dodge)
2.0-liter, new transmission software (1996-97), Apr.59-60
2.5-liter, head gasket running change (1995-2000), Jun.66
intermittent cruise control (1995-99), Oct.28
PCM reflashing tips (1995-99), Dec.50
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
B-3000 (Mazda), coolant and/or refrigerant leak (1998), Dec.48
B-series (Mazda)
ABS light on, with DTC 5 (1997), Aug.59
rattling exhaust (1991-94), Oct.26
Beretta (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
new diagnostic tables (1996), Feb.69
Blazer (Chevrolet), inoperative heated front passenger seat (1998), Aug.59
BMW, replacing receiver/dryers, Jun.70
Bonneville (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Boxster (Porsche)
power steering belt squeal (1997), Jul.71-72
squeaky pedals (1997 on), Mar.85
Bravada (Oldsmobile)
4.3-liter
dead battery, alternator not charging (1998), Jun.74
ticking noise underneath (1997-98), Jul.70
5-liter, ticking noise underneath (1997-98), Jul.70
7.4-liter, ticking noise underneath (1997-98), Jul.70
inoperative heated front passenger seat (1998), Aug.59
Breeze (Plymouth)
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
Bronco (Ford), PCM reprogramming flash cable available (1996), Feb.72
C-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
C/K-body truck (Chevrolet/GMC)
4.3-liter, EGR valve recall (1996-97), Mar.82-83
5-liter, EGR valve recall (1996-97), Mar.82-83
5.7-liter, EGR valve recall (1996-97), Mar.82-83
brake pull and premature front pad wear (1992-99), May.70-71
climate control knobs spin (1996-97), Jul.73
clutch pedal separates (1997), Sep.68
fuel gauge fluctuation (1995-97), Oct.28
rear axle leak (1992-96), Dec.50
"shrinking" gas tank (1995-97), Nov.75
C70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
Cab Chassis (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Cabrio (Volkswagen)
incorrect spark plug application listings (1991 on), Jun.62
oil overfill caution (latest generation), Dec.52
Cabriolet (Audi), MIL on, various EGR DTCs (1995), Sep.75
Camaro (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, spark knock at idle (1995-96), Dec.52
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1998-99), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
engine miss, poor driveability (1993-97), Jun.63
Camry (Toyota)
3-liter, DTC P1133, MIL illuminated (1997-99), Nov.79
poor driveability when cold (1988-89), Mar.84
steering gear service precaution (1996 newer), Dec.50
Caprice (Chevrolet), engine miss, poor driveability (1994-96), Jun.63
Caravan (Dodge)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
CarHelp.com, website address, May.79
Catera (Cadillac), evap system leak (1997), Apr.57-58
Cavalier (Chevrolet)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1996-97), Feb.69
Celica (Toyota), steering gear service precaution (1996 newer), Dec.50
Century (Buick)
3.1-liter, premature cranking with new PCM (1997), Apr.58
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, premature cranking with new PCM (1997), Apr.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73

2000 Motor Magazine Index

shaking sensation on smooth roads (1997-99), Oct.26
wipers don't park correctly (1997-98), Jun.69
Cherokee (Jeep)
4-liter, scraping noise in engine compartment, radiator leak (1998), Sep.76
false MIL with various DTCs (1997), Nov.79
headlight flicker (1997-99), May.78
PCM reflashing tips (1995-99), Dec.50
scraping noise under hard braking (1993-97), Dec.52, 56
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1995-99), Mar.84-85
Chrysler
a/c odor (prior to 1998), Jun.62
41TE/42LE transaxle, a/c bump, DTC 73 caused by TCC chatter (1996), Aug.60
Cirrus (Chrysler)
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
Civic (Honda)
bad voltage regulator (1997-98), Jun.70
frozen condenser fan (1996-98), Feb.70-71
CK-body truck (Chevrolet/GMC)
4.3-liter, ticking noise underneath (1997-98), Jul.70
5-liter, ticking noise underneath (1997-98), Jul.70
7.4-liter, ticking noise underneath (1997-98), Jul.70
Clevite Engine Parts, Victor Reinz master gaskets catalog, Oct.30
Concorde (Chrysler)
a/c leak (1995-97), Nov.79
2.7-liter, noisy tensioner (1998), Nov.78
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
new transmission software (1996-97), Apr.59-60
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Concours (Cadillac), oil ring installation revision (1994-97), Aug.61
Continental (Lincoln)
ABS noise (1998-99), Jun.74
automatic transmission identification (1988-96), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
Moog Automotive, improved non-greasable front stabilizer bar link (1988-94), Apr.54
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
popping noise in front end (1988-94), Jan.60
ticking noise from transaxle (1995), Mar.86
transmission DTCs stored in memory (1998), May.76
Contour (Ford)
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-99), Feb.72
Contour SVT (Ford), steering pull/drift to the right (1998-99), Oct.26
Corolla (Toyota), steering gear service precaution (1996 newer), Dec.50
Corrado (Volkswagen), 2.8-liter, rough idle, poor performance (1992-94), Mar.85
Corrado SLC (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Corsica (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
new diagnostic tables (1996), Feb.69
Corvette (Chevrolet)
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
engine miss, poor driveability (1992-96), Jun.63
Cougar (Mercury)
3.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
4.6-liter, PCM reprogramming flash cable available (1994-97), Feb.72
blower motor squeak/chirp (1989-97), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1994-98), Aug.59
PCM reprogramming flash cable available (1999), Feb.72
transmission DTCs stored in memory (1997), May.76
Contour (Ford), 2.5-liter, MIL on, DTCs stored (1996-98), Jul.72-73
CR-V (Honda), clunking from power windows (1997-98), Jul.71
Crew Cab (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Crown Victoria (Ford)
4.6-liter, no crank (1992-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
stall during acceleration and/or turning (1996), Jun.65-66
transmission DTCs stored in memory (1998), May.76
Cutlass (Oldsmobile)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.4-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1997), Feb.69
Cutlass Ciera (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
Cutlass Cruiser (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Cutlass Supreme (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Dakota (Dodge)
3.9-liter, ignition crossfire (1994-99), Feb.71-72
5.2-liter, ignition crossfire (1994-99), Feb.71-72
5.9-liter, ignition crossfire (1994-99), Feb.71-72
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
Daytona (Dodge), intermittent cruise control (1990-93), Oct.28
Defender (Land Rover)
3.9-liter, hard start in cold weather (1993-95), May.73
O2 sensor codes (1997), Feb.69-70
DeVille (Cadillac)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
intermittent Neutral on the highway (1995), Sep.73
leaky oil cooler lines (1993-98), Dec.52
oil ring installation revision (1994-97), Aug.61
DeVille D'Elegance (Cadillac), oil ring installation revision (1997), Aug.61
Diamante (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
Discovery (Land Rover)
3.9-liter
hard start in cold weather (1993-95), May.73
wrong ignition timing (1994), Apr.56
bad heater hose (1997), May.78
camshaft knock (1994-95), Jan.61-62
engine surge while coasting (1997), Oct.27
MIL on, DTC P0451 (1997 newer), Apr.64-65
O2 sensor codes (1996-98), Feb.69-70
Durango (Dodge)
3.9-liter, ignition crossfire (1998-99), Feb.71-72
5.2-liter, ignition crossfire (1998-99), Feb.71-72
5.9-liter, ignition crossfire (1998-99), Feb.71-72
bucking at wide open throttle (1998), Nov.76-77
PCM reflashing tips (1998-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
Dynasty (Dodge), intermittent cruise control (1989-93), Oct.28
E-250 (Ford), 4.2-liter, exhaust booming noises (1997-98), Dec.52
E-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
Halogen/Xenon headlight repair kits (1996 on), May.71
E420 (Mercedes-Benz), automatic transmission fluid caution (1996), Apr.64
Econoline (Ford)
4.2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.6-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
4.9-liter, PCM reprogramming flash cable available (1996), Feb.72
5-liter, PCM reprogramming flash cable available (1996), Feb.72
5.4-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
5.8-liter, PCM reprogramming flash cable available (1996), Feb.72
6.8-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
PCM reprogramming flash cable available (1997-99), Feb.72
7.3-liter turbodiesel, PCM reprogramming flash cable available (1995-99), Feb.72
7.5-liter, PCM reprogramming flash cable available (1996), Feb.72
binding ignition key (1997-99), Nov.75
delayed upshift from reman 4R70W, DTC P0782 (1994-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, no symptoms (1997), Apr.63-64
steering column squeak/moan (1992-99), Jun.74
transmission DTCs stored in memory (1997-98), May.76
Eighty Eight (Oldsmobile), intermittent Neutral on the highway (1995-97), Sep.73
Elantra (Hyundai)
revised TCMs (1996), Nov.75-76
timing chain noise (1996-98), Jun.68
Eldorado (Cadillac)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
leaky oil cooler lines (1993-98), Dec.52
oil ring installation revision (1993-97), Aug.61
ES 300 (Lexus), outside temperature reads -22o F (1993-96), Dec.56
ES 400 (Lexus), inaccurate outside temperature display (1995-96), Jun.69
Escort (Ford)
1.9-liter, PCM reprogramming flash cable available (1996), Feb.72
2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
blower motor squeak/chirp (1991-97), Aug.58, Nov.78
brake noise (1997-99), Jul.68
front brake knocking noise (1991-96), Oct.28
Escort ZX2 (Ford), brake noise (1998-99), Jul.68
Eurovan (Volkswagen)
axle shaft service (all years), May.77-78
modified cam drive chain (1997 and on), May.72
oil overfill caution (latest generation), Dec.52
Expedition (Ford)
4.6-liter
high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
high idle, sticking throttle (1997-98), May.72-73
5.4-liter, high fast idle with MIL illuminated and DTC stored (1997-98), Apr.57
ABS light on (1997-99), Oct.24
air suspension light on (1997-99), Jun.69
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1997-99), Feb.72
transmission DTCs stored in memory (1998), May.76
Explorer (Ford)
4-liter
acceleration "whoosh" (1997), Jun.61
hesitation, harsh downshift (1997-99), Jan.62-63
5-liter, hesitation, harsh downshift (1997-99), Jan.62-63
delayed upshift from reman 4R70W, DTC P0782 (1996-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, DTCs, O2 sensor leak (1996-

98), Dec.56
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
Express (Chevrolet), 4.3-liter, slower-than-normal downshifts (1997), Jun.66
F-150 (Ford)
4.6-liter, high idle, sticking throttle (1997-98), May.72-73
ABS light on (1997-99), Oct.24
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1994-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998). Sep.70, 72
transmission DTCs stored in memory (1997-98), May.76
F-250 (Ford)
4.6-liter, high idle, sticking throttle (1997-98), May.72-73
fuel pump service tip (1998), Sep.70, 72
F-250 HD (Ford), stall after long deceleration (1997), Sep.74-75
F-250 LD (Ford)
ABS light on (1997-99), Oct.24
binding ignition key (1997-99), Nov.75
blower motor squeak/chirp (1997), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
transmission DTCs stored in memory (1997-98), May.76
F-350 (Ford), stall after long deceleration (1997), Sep.74-75
F-Series (Ford)
4.2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.6-liter, PCM reprogramming flash cable available (1997-99), Feb.72
4.9-liter, PCM reprogramming flash cable available (1996), Feb.72
5-liter, PCM reprogramming flash cable available (1996), Feb.72
5.4-liter, PCM reprogramming flash cable available (1997-99), Feb.72
5.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
6.8-liter
PCM reprogramming flash cable available (1994-99), Feb.72
PCM reprogramming flash cable available (1999), Feb.72
7.3-liter turbodiesel, PCM reprogramming flash cable available (1994-99), Feb.72
7.5-liter, PCM reprogramming flash cable available (1996-97), Feb.72
Firebird (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, spark knock at idle (1995-96), Dec.52
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1998-99), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
3100/3400/3800, hard-start/no-start (1996), Jan.62
engine miss, poor driveability (1993-97), Jun.63
Fleetwood (Cadillac), engine miss, poor driveability (1994-96), Jun.63
Ford, proper grade of motor oil (1989 on), Sep.70
G-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
climate control knobs spin (1996-97), Jul.73
G-van (Chevrolet/GMC), brake pull and premature front pad wear (1996-99), May.70-71
Galant (Mitsubishi), coolant service (1994-96), Jan.63
General Motors
automatic headlights and DRL retrofits (1996 and older with some exceptions), Nov.78-79
evaporator odor in all cars and light duty trucks except Geo and Tracker, May.75
exterior light leakage/condensation (1993-99), Feb.72
new PCM connector service kits (1996-99), Mar.88
wrong PCV maintenance schedules (1994-98), Aug.60
Golf (Volkswagen)
inoperative cruise control (1995), Jul.72
oil overfill caution (latest generation), Dec.52
vibrating/knocking shift lever (1999), Sep.73-74
Golf III (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Grand Am (Pontiac)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
Grand Cherokee (Jeep)
3.9-liter, ignition crossfire (1994-98), Feb.71-72
5.2-liter
DTC P1494 and/or MIL on (1997-98), Apr.61
ignition crossfire (1994-98), Feb.71-72
5.9-liter
DTC P1494 and/or MIL on (1997-98), Apr.61
ignition crossfire (1994-98), Feb.71-72
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
horn service (1997-98), Jul.68
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1993-98), Mar.84-85, Oct.26
Grand Marquis (Mercury)
4.6-liter, no crank (1992-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
stall during acceleration and/or turning (1996), Jun.65-66
transmission DTCs stored in memory (1997), May.76
Grand Prix (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
wipers don't park correctly (1997-98), Jun.69
Grand Wagoneer (Jeep), transfer case shifter noise (1993-98), Mar.84-85, Oct.26
GS 300 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22o F (1993-96), Dec.56
GTI (Volkswagen), inoperative cruise control (1995), Jul.72
I30 (Infiniti)
no start, MIL on, electrical glitches (1996-99), Dec.52
rear brake groan/hum (1996-99), Oct.28
Imperial (Chrysler), intermittent cruise control (1990-93), Oct.28
Integra (Acura), rear-end squeak (1990 newer), Apr.61, 63
Intrepid (Dodge)
a/c leak (1995-97), Nov.79
2.7-liter, noisy tensioner (1998), Nov.78
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
new transmission software (1996-97), Apr.59-60
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Intrigue (Oldsmobile)
3.5-liter, bellhousing bolt precaution (1999), Apr.54
wipers don't park correctly (1998), Jun.69
Isuzu, revised water pump procedure, Dec.48
J-car (General Motors), ABS light on (1992-97), Dec.56
Jaguar, pressure switch replacement (prior to 1992), Jan.63
Jetta (Volkswagen)
2.8-liter, rough idle, poor performance (1992-94), Mar.85
inoperative cruise control (1995), Jul.72
oil overfill caution (latest generation), Dec.52
vibrating/knocking shift lever (1999), Sep.73-74
Jetta GLX (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Jetta III (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Jimmy (GMC), inoperative heated front passenger seat (1998), Aug.59
K1500 (General Motors), delayed or no front axle engagement (1988-97), Apr.60-61
K2500 (General Motors), delayed or no front axle engagement (1988-97), Apr.60-61
K3500 (General Motors), delayed or no front axle engagement (1994-97), Apr.60-61
L-car (General Motors), ABS light on (1991-96), Dec.56
Land Cruiser (Toyota)
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
LeBaron (Chrysler)
3-liter, harsh shifting (1992-95), Feb.69
front power window won't go up (1994-95), May.77
intermittent cruise control (1989-95), Oct.28
PCM reflashing tips (1995), Dec.50
LeBaron Convertible (Chrysler)
intermittent cruise control (1990-95), Oct.28
PCM reflashing tips (1995), Dec.50
LeBaron Coupe (Chrysler), intermittent cruise control (1990-95), Oct.28
LeSabre (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Lexus, a/c compressor damage in stored vehicles, Oct.26-27
LHS (Chrysler)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
power steering noise (1998-99), Sep.70
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
LS 400 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
more durable blower motor (1998-99), Nov.79
outside temperature reads -22o F (1993-96), Dec.56
LSS (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Lumina APV (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-96), Sep.73
Lumina (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, power steering shudder (1998-99), Mar.85-86
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
LX 470 (Lexus), more durable blower motor (1998-99), Nov.79
M/L-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
M3 (BMW), 3.2-liter, proper thermostat replacement (1998 newer), Dec.50
Malibu (Chevrolet)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.4-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1997), Feb.69
Mark VIII (Lincoln)
blower motor squeak/chirp (1993-97), Aug.58, Nov.78
delayed upshift from reman 4R70W, DTC P0782 (1993-98), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1996-98), Feb.72
transmission DTCs stored in memory (1997), May.76
Maserati TC (Chrysler), intermittent cruise control (1990-91), Oct.28
Mercedes-Benz, automatic transmission fluid caution (1997

2000 Motor Magazine Index

newer), Apr.64
Millenia (Mazda)
MIL on with DTCs P0300 through P0306 (1997-98), Sep.70
piston standardization (1995-99), Nov.77-78
Mirage (Mitsubishi), coolant service (1993-96), Jan.63
ML320 (Mercedes-Benz), low range light on (1998), Feb.69
Monte Carlo (Chevrolet)
3.4-liter, hard-start/no-start (1996), Jan.62
3.8-liter, power steering shudder (1998-99), Mar.85-86
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Montero (Mitsubishi)
3-liter, engine bearing ID (1996-96), Nov.79
coolant service (1992-96), Jan.63
Mountaineer (Mercury)
4-liter, hesitation, harsh downshift (1997-99), Jan.62-63
5-liter, hesitation, harsh downshift (1997-99), Jan.62-63
delayed upshift from reman 4R70W, DTC P0782 (1993-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
MIL on, DTCs, O2 sensor leak (1997-98), Dec.56
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1997-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
MR2 (Toyota), steering gear service precaution (1996 newer), Dec.50
Mustang (Ford)
3.8-liter, PCM reprogramming flash cable available (1994-99), Feb.72
4.6-liter, PCM reprogramming flash cable available (1996-99), Feb.72
blower motor squeak/chirp (1994-97), Aug.58, Nov.78
clutch vibration (1991-98), Nov.76
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
transmission DTCs stored in memory (1998), May.76
MX-5 Miata (Mazda), MIL on, DTC P0300 (1997), Jul.70
MX-6 (Mazda), dead power driver's seat (1993-94), Jan.63
Mystique (Mercury)
2.5-liter, MIL on, DTCs stored (1996-98), Jul.72-73
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
PCM reprogramming flash cable available (1996-99), Feb.72
N-car (General Motors), ABS light on (1991-96), Dec.56
Navajo (Mazda), rattling exhaust (1991-94), Oct.26
Navigator (Lincoln)
5.4-liter, high fast idle with MIL illuminated and DTC stored (1998), Apr.57
ABS light on (1998-99), Oct.24
air suspension light on (1997-99), Jun.69
binding ignition key (1998-99), Nov.75
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1998-99), Feb.72
transmission DTCs stored in memory (1997-98), May.76
Neon (Dodge/Plymouth)
2-liter, misfire DTCs with no symptoms (1997-99), May.70
bouncing tach (1997-98), Jul.68
cam sensor oil leak (1995-99), Jan.60-61
cooling fan quits or won't stop running (1997-98), Oct.24
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
New Beetle (Volkswagen)
new alignment specs (1998 on), Nov.79
oil overfill caution (latest generation), Dec.52
unnecessary body computer replacement (1998 and newer), Apr.60
New Yorker (Chrysler)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1989-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
New Yorker Fifth Avenue (Chrysler), intermittent cruise control (1990-93), Oct.28
New Yorker Salon (Chrysler), intermittent cruise control (1989-93), Oct.28
Ninety Nine (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Ninety Nine Regency (Oldsmobile), intermittent Neutral on the highway (1995-96), Sep.73
Nissan, cranks but won't start troubleshooting procedure, Oct.27-28
P-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
Park Avenue (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
brake noise (1997-98), Jul.68
intermittent Neutral on the highway (1995-96), Sep.73
Parts Plus, 2000 Parts Plus Guide to NASCAR, May.79
Paseo (Toyota), steering gear service precaution (1996 newer), Dec.50
Passat (Volkswagen)
2.8-liter, rough idle, poor performance (1992-94), Mar.85
oil overfill caution (latest generation), Dec.52
unnecessary body computer replacement (1998 and newer), Apr.60
vibrating/knocking shift lever (1997), Sep.73-74
Passat GLX (Volkswagen), incorrect spark plug application listings (1991 on), Jun.62
Pickup (Mitsubishi), 3-liter, engine bearing ID (1996-96), Nov.79
Prelude (Honda), clunking from power windows (1997-98), Jul.71
Previa (Toyota)
improved rear a/c magnetic valve (1991-97), Apr.55
steering gear service precaution (1996 newer), Dec.50
Probe (Ford), 2-liter, PCM reprogramming flash cable available (1996-97), Feb.72
Prowler (Plymouth)
3.5-liter, fuel system recall (1997), Mar.83
cold-start sputtering (1997), Sep.73
PCM reflashing tips (1997-99), Dec.50
Ram (Dodge)
3.9-liter, ignition crossfire (1994-99), Feb.71-72
5.2-liter, ignition crossfire (1994-99), Feb.71-72
5.9-liter, ignition crossfire (1994-99), Feb.71-72
clunk/rattle in steering column (1994-95), Mar.85
injection pump tampering (1994-97), Jan.58
sluggish acceleration, false MIL (1998-99), May.73-74
steering column noise (1994-97), Apr.54
Ram pickup (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1995-96), Dec.56
asbestos brakes (1997-99), Jun.74
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
squeak from rear leaf springs (1994-99), Sep.68
Ram Van (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1992-96), Dec.56
asbestos brakes (1995-97), Jun.74
bucking at wide open throttle (1996-98), Nov.76-77
false MIL with various DTCs (1997), Nov.79
front end clunk (1995-97), Feb.70
no crank (1994-97), Sep.76
PCM reflashing tips (1995-99), Dec.50
sluggish acceleration, false MIL (1998-99), May.73-74
squeak from rear leaf springs (1994-99), Sep.68
Ram Wagon (Dodge)
(5.2-liter compressed natural gas), long crank time, low power when cold (1992-96), Dec.56
asbestos brakes (1995-97), Jun.74
false MIL with various DTCs (1997), Nov.79
front end clunk (1995-97), Feb.70
no crank (1994-97), Sep.76
sluggish acceleration, false MIL (1998-99), May.73-74
squeak from rear leaf springs (1994-99), Sep.68
Range Rover (Land Rover)
3.9-liter, wrong ignition timing (1994), Apr.56
leaking transfer case output seals (prior to 1998), Apr.63
Range Rover Classic (Land Rover)
3.9-liter
camshaft knock (1994-95), Jan.61-62
hard start in cold weather (1993-95), May.73
4.2-liter, hard start in cold weather (1993-95), May.73
Ranger (Ford)
fuel pump service tip (1998), Sep.70, 72
high idle during closed-throttle decel (1998-99), Jul.73
PCM reprogramming flash cable available (1995-99), Feb.72
power window drops only 5 inches (1998), Nov.79
transmission DTCs stored in memory (1997-98), May.76
whistling/hissing from transmission (1997-98), Aug.59
Regal (Buick)
3.1-liter, premature cranking with new PCM (1997), Apr.58
3.8-liter, premature cranking with new PCM (1997), Apr.58
intermittent Neutral on the highway (1995-97), Sep.73
shaking sensation on smooth roads (1997-99), Oct.26
wipers don't park correctly (1997-98), Jun.69
Riviera (Buick)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
brake noise (1997-98), Jul.68
intermittent Neutral on the highway (1995-96), Sep.73
Roadmaster (Buick), engine miss, poor driveability (1994-96), Jun.63
Rodeo (Isuzu)
3.2-liter
updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
valvetrain tick (1997 and earlier), Dec.57
inoperative speedometer (1991-96), Jun.62
rear axle leaks (1998-99), Aug.58-59
RVA4 (Toyota), steering gear service precaution (1996 newer), Dec.50
RX 300 (Lexus), false DTC P0446 (1999), Apr.64
RX300 (Lexus), front brake squeal (1999), Jul.73
S-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
automatic transmission fluid caution (1996), Apr.64
no crank, blown cigarette lighter fuse (1994-95), Apr.56
S/T-body truck (Chevrolet/GMC)
4.3-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5-liter
EGR valve recall (1996-97), Mar.82-83
ticking noise underneath (1997-98), Jul.70
5.7-liter, EGR valve recall (1996-97), Mar.82-83
7.4-liter, ticking noise underneath (1997-98), Jul.70
dead battery, alternator not charging (1998), Jun.74
horn blaring or fuel pump runs continuously after heavy rain or car wash (1998), Oct.28
S70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
S90 (Volvo), revised power steering parts (1997), Nov.78
Saab, special ignition tool, Jan.61
Sable (Mercury)
3-liter
automatic transmission identification (1994-96), Mar.83
hesitation, delayed downshift (1996-97), Jun.63
ABS noise (1998-99), Jun.74
automatic transmission identification (1986 on), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Moog Automotive, improved non-greasable front stabilizer bar link (1986-95), Apr.54
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
popping noise in front end (1986-95), Jan.60
rear tire wear (1996-97), May.78
transmission DTCs stored in memory (1998), May.76
Safari (GMC), climate control knobs spin (1996-97), Jul.73
Saturn
intermittent no click, no crank, no start (1998), Oct.26
transaxle valve body cover gasket service (1991-96), Sep.70
Savanna (GMC), 4.3-liter, slower-than-normal downshifts (1997), Jun.66
SC 300 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22o F (1993-96), Dec.56
SC 400 (Lexus)
inaccurate outside temperature display (1995-96), Jun.69
outside temperature reads -22o F (1993-96), Dec.56
Scott Specialty Gases, Design & Safety handbook for Specialty Gas Delivery Systems, Oct.30
Sebring (Chrysler)
2.0-liter, new transmission software (1996-97), Apr.59-60
2.5-liter, head gasket running change (1995-2000), Jun.66
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28

2000 Motor Magazine Index

PCM reflashing tips (1995-99), Dec.50
power steering noise (1996-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
Sebring Convertible (Chrysler)
intermittent cruise control (1996-99), Oct.28
PCM reflashing tips (1996-99), Dec.50
Seville (Cadillac)
4-liter, updated fuel pressure readings (1998), May.72
4.6-liter
coolant leak (2000), Nov.78
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
leaky oil cooler lines (1993-97), Dec.52
oil ring installation revision (1993-97), Aug.61
Shadow (Dodge), intermittent cruise control (1992-94), Oct.28
Sidekick Sport (Suzuki)
front end squeaks and clunks (1996 on), Mar.83-84
TPS service (all years), May.77
two different PCMs (1995-96), Sep.73
Sidekick (Suzuki), front end squeaks and clunks (1991 on), Mar.83-84
Sienna (Toyota), steering gear service precaution (1996 newer), Dec.50
Sierra (GMC)
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1999), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
Silhouette (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Silverado (Chevrolet)
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1999), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
Skylark (Buick)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
SL-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
automatic transmission fluid caution (1996), Apr.64
SLX (Acura), engine and transmission Mills on (1996), Jun.68
Sonata (Hyundai)
2-liter, rough idle, harsh up and downshifting, engine speed fluctuation (1996-97), Oct.26
3-liter, rough idle, harsh up and downshifting, engine speed fluctuation (1995-97), Oct.26
revised TCMs (1995-96), Nov.75-76
Spirit (Dodge)
3-liter, harsh shifting (1992-95), Feb.69
intermittent cruise control (1989-95), Oct.28
PCM reflashing tips (1995), Dec.50
Stratus (Dodge)
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
Subaru, towing tip, Mar.86
Suburban (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Sundance (Plymouth), intermittent cruise control (1992-94), Oct.28
Sunfire (Pontiac)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1996-97), Feb.69
Supra (Toyota), steering gear service precaution (1996 newer), Dec.50
T100 (Toyota)
cylinder head service (1988-95), Apr.65
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
Tacoma (Toyota)
2.4-liter, lumpy idle (1995-97), Aug.59
buzzing evap canister (1995-96), Nov.75
snow in HVAC box (1996-98), May.76
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
Talon (Eagle)
2.0-liter, new transmission software (1996-97), Apr.59-60
intermittent cruise control (1995-99), Oct.28
PCM reflashing tips (1995-99), Dec.50
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
Taurus (Ford)
3-liter
automatic transmission identification (1994-96), Mar.83
hesitation, delayed downshift (1996-97), Jun.63
3.4-liter, automatic transmission identification (1996), Mar.83
ABS noise (1998-99), Jun.74
automatic transmission identification (1986 on), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Moog Automotive, improved non-greasable front stabilizer bar link (1986-95), Apr.54
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
popping noise in front end (1986-95), Jan.60
rear tire wear (1996-97), May.78
transmission DTCs stored in memory (1998), May.76
Taurus SHO (Ford), lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Tempo (Ford)
2.3-liter, MIL on with no driveability problems (1988-94), Feb.68-69
3-liter, MIL on with no driveability problems (1992-94), Feb.68-69
blower motor squeak/chirp (1984-94), Aug.58, Nov.78
Tercel (Toyota), steering gear service precaution (1996 newer), Dec.50
Thunderbird (Ford)
3.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
4.6-liter, PCM reprogramming flash cable available (1994-99), Feb.72
blower motor squeak/chirp (1989-97), Aug.58, Nov.78
delayed upshift from reman 4R70W (1994-97), Aug.59
transmission DTCs stored in memory (1997), May.76
Tiburon (Hyundai)
revised TCMs (1997), Nov.75-76
timing chain noise (1997-98), Jun.68
Topaz (Mercury)
2.3-liter, MIL on with no driveability problems (1988-94), Feb.68-69
3-liter, MIL on with no driveability problems (1992-94), Feb.68-69
blower motor squeak/chirp (1984-94), Aug.58, Nov.78
Town & Country (Chrysler)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
Town Car (Lincoln)
4.6-liter, no crank (1991-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997), May.70
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
transmission DTCs stored in memory (1998), May.76
Tracer (Mercury)
1.9-liter, PCM reprogramming flash cable available (1996), Feb.72
2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
blower motor squeak/chirp (1991-97), Aug.58, Nov.78
brake noise (1997-99), Jul.60, 68
front brake knocking noise (1991-96), Oct.28
Tracker (Chevrolet/Geo), lack of power in snowstorms (1996-97), Oct.27
Trans Am (Pontiac), engine miss, poor driveability (1993-97), Jun.63
Trans Sport (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Trooper (Isuzu)
3.2-liter
updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
valvetrain tick (1997 and earlier), Dec.57
truck (Dodge), no charge condition (1996-98), Nov.75
truck (Toyota), cylinder head service (1988-95), Apr.65
V70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
V90 (Volvo), revised power steering parts (1997), Nov.78
Ventura (Chevrolet), intermittent Neutral on the highway (1997), Sep.73
Villager (Mercury)
blower motor squeak/chirp (1993-97), Aug.58, Nov.78
temperature display oddity (1996-98), Apr.56
Viper (Dodge), PCM reflashing tips (1995-99), Dec.50
Vision (Eagle)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Voyager (Plymouth)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
Windstar (Ford)
ABS noise (1998-99), Jun.74
automatic transmission identification (1995 on), Mar.83
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1995-99), Feb.72
Wrangler (Jeep)
false MIL with various DTCs (1997), Nov.79
no charge condition (1997-98), Nov.75
PCM reflashing tips (1995-99), Dec.50
slow fuel fill-up (prior to 11/22/96), Jan.60
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1997-99), Mar.84-85
XJ8 (Jaguar)
higher idle speeds (1998 newer), Jun.64-65
intermittent dash lights with false warnings (1998), Dec.52
transmission recall/replacement (1999), Jun.62
XJ12 (Jaguar), waterlogged PCM (1995), May.77
XJS (Jaguar), stuck throttle on cold engine (1995-96), May.71-72
XK8 (Jaguar)
higher idle speeds (1997 newer), Jun.64-65
intermittent dash lights with false warnings (1998), Dec.52
transmission recall/replacement (1999), Jun.62
XRJ (Jaguar), waterlogged PCM (1995), May.77
Z3 (BMW)
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1997), Apr.57
Service Technicians Society (STS)
2000 World Congress, Apr.49
employment section added to website, Dec.64
OBDII training video, Jun.52-53
Seville (Cadillac)
4-liter, updated fuel pressure readings

2000 Motor Magazine Index

(1998), May.72
4.6-liter
coolant leak (2000), Nov.78
poor a/c performance (1994-96), Oct.24
updated fuel pressure readings (1998), May.72
4.9-liter, poor a/c performance (1994-96), Oct.24
brake noise (1997-98), Jul.68
fuel odor, MIL on (1997), May.75
leaky oil cooler lines (1993-97), Dec.52
oil ring installation revision (1993-97), Aug.61
Shadow (Dodge), intermittent cruise control (1990-95), Oct.28
Shenandoah Manufacturing, Horizon waster oil heaters, Dec.65
Shop management
advertising
choosing media, Mar.74
creating a budget, Mar.74
determining budget chart, Mar.73
establishing objectives, Mar.74
fighting negative image of automotive aftermarket industry, Aug.46-50
How to be a Media-Savvy Shop Owner, Aug.46-50
insurance, not taking coverage for granted, Jun.10, 13, 15
knowing your competition, Sep.57-60
marketing
creating a company vision, Mar.71-72
evaluating your business name and logo, Mar.72-73
evaluating your customer database, Mar.73-74
examining the appearance of your shop, Mar.73
FirstStrike, marketing components, Jun.75
PageViews marketing website, Nov.80
reception and waiting area checklist, Mar.72
Ten Surefire Strategies to Lose The Battle of the Bays, Jun.2
tracking marketing results, Mar.74
media
contacting, Aug.48
establishing your agenda, Aug.47-48
making your points, Aug.49-50
providing access/information, Aug.48
when they contact you, Aug.50
regulations, waste oil disposal, Jan.44-46, 48-49
scheduled maintenance
filling lulls with "elective" jobs, Mar.10, 12-13
importance of, Feb.28-29
software, Jazz Design AUTOS2000 Automotive Shop Management new software features, Jul.74
technicians
common hand problems encountered by technicians, Jul.30, 32
Getting to Know You questionnaire, Jun.47
hand care guidelines, Jul.30
interaction with co-workers, Mar.10, 12-13
staying qualified, Jun.45-48
Sidekick Sport (Suzuki)
front end squeaks and clunks (1996 on), Mar.83-84
TPS service (all years), May.77
two different PCMs (1995-96), Sep.73
Sidekick (Suzuki), front end squeaks and clunks (1991 on), Mar.83-84
Siemens Automotive, Daimler Chrysler CHEER Award received, Mar.89
Sienna (Toyota), steering gear service precaution (1996 newer), Dec.50
Sierra (GMC)
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1999), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
Silhouette (Oldsmobile)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Silverado (Chevrolet)
2000 Light Truck Service Report, Jan.37-38
4.8-liter, second design connecting rod bolt (1999), Aug.58
5.3-liter, second design connecting rod bolt (1999), Aug.58
5.7-liter, second design connecting rod bolt (1999), Aug.58
6-liter, second design connecting rod bolt (1999), Aug.58
SK Hand Tool
metric impact socket set, Oct.35
new website, Mar.89
Skylark (Buick)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
new diagnostic tables (1996-97), Feb.69
SL-Class (Mercedes-Benz)
2.8-liter, sticky EGR valve (1994), Mar.88
3.2-liter, sticky EGR valve (1994), Mar.88
automatic transmission fluid caution (1996), Apr.64
SLX (Acura), engine and transmission MILs on (1996), Jun.68
Smart & Savvy, Chrysler's new 45RFE transmission explained, Jun.35-38
Snap-on Diagnostics
1999 Fast-Track Domestic Transmission Troubleshooter Cartridge, Dec.65
kV Secondary Ignition Module, Sep.28, 30
secondary ignition tester for Vantage, May.81
SIS 900 Service Inspection System, Nov.46
Snap-on Incorporated, Internet B2B e-commerce alliance formed with Genuine Parts, Apr.50
Snap-on Tools
High Strength Sealed Ratchet Series, Oct.35
Latch-on Ratcheting Box Wrenches, Sep.36
pledge to Automotive Management Institute's Excel 2000 program, Apr.66
product line available on line, Nov.80
snap ring plier set, Nov.81
Soft Grip Ratcheting Screwdriver, Sep.78
Society of Automotive Engineers (SAE)
2000 World Congress, Apr.49
Performance Review Institute, Mobile Air Conditioning Society (MACS), rating system and certification program, Apr.23
Software
see also Computers; Internet
3-D mapping, Dec.20, 22
on-board computer software adds greater safety features to new vehicles, Sep.22, 24
Sonata (Hyundai)
2-liter, rough idle, harsh up and downshifting, engine speed fluctuation (1996-97), Oct.26
3-liter, rough idle, harsh up and downshifting, engine speed fluctuation (1995-97), Oct.26
revised TCMs (1995-96), Nov.75-76
Source Guide 2000, on-line, Jan.52-53
Specialty Equipment Market Association (SEMA)
Automotive Aftermarket Industry Week (AAIW), Sep.77
Global Automotive Aftermarket Symposium (GAAS), Jun.2
Speedometers, checking with dynamometers, Nov.45
Spirit (Dodge)
3-liter, harsh shifting (1992-95), Feb.69
intermittent cruise control (1989-95), Oct.28
PCM reflashing tips (1995), Dec.50
Sprocket (Honda), concept vehicle unveiled at 2000 North American International Auto Show, Mar.79-80
SPX Corp.
Bear/Allen Emissary Series dynamometers, Nov.46-47
Cash in on America's Favorite Tools promotion, Jun.75
SPX Service Solutions, use of NASA technology for emission monitoring remote sensor, Sep.66
SSR (Chevrolet), concept vehicle unveiled at 2000 North American International Auto Show, Mar.77
Steering & suspension
checking the basics, Mar.66, 69
checking tires for excessive, unusual or uneven wear, Mar.70
the customer complaint, Mar.65-66
OE Scheduled Maintenance Handbook Tech Tips, Feb.52-53
Steering and Suspension Assessment quiz, Mar.67-68
Truck (General Motors), breaking loose the ball joint/control arm rivets, Jul.4
undercar inspection, Mar.69-70
Stereo systems
Digital Audio Broadcasting (DAB), Jan.26
Honda/OnStar/XM Satellite Radio team up to offer mobile communication services, Jul.62-63
In-Band, On Channel, Digital Audio Broadcasting (IBOC DAB), Jan.29
S-band technology, Internet access, Jan.28-29
Stockhausen Hand Care System
Kresto EF Hand Cleaner, comparison, Jul.34
Stockolan, comparison, Jul.34
Travabon, comparison, Jul.34
Stratus (Dodge)
2001 Domestic Tech Preview, Nov.30, 32
2.5-liter, head gasket running change (1995-2000), Jun.66
asbestos brakes (1995), Jun.74
cam sensor oil leak (1995-99), Jan.60-61
front end rumble (1997-98), Jul.72
intermittent cruise control (1995-99), Oct.28
new transmission software (1996-97), Apr.59
PCM reflashing tips (1995-99), Dec.50
power steering noise (1995-98), Sep.70
single-cylinder misfire (1995-96), Dec.48
STS, White Lithium Plus lubricant, Sep.80
STS see Service Technicians Society (STS)
Subaru, towing tip, Mar.86
Suburban (Chevrolet), 2000 Light Truck Service Report, Jan.37-38
Suburban (Chevrolet/GMC), brake pull and premature front pad wear (1992-99), May.70-71
Sundance (Plymouth), intermittent cruise control (1990-95), Oct.28
Sunfire (Pontiac)
2.2-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
2.3-liter, rough running, high oil pressure (1995-97), Jan.58, 60
2.4-liter
rough running, high oil pressure (1995-97), Jan.58, 60
slow starting, warning lights, driveability trouble (1997-98), Jun.62
3.1-liter, slow starting, warning lights, driveability trouble (1997-98), Jun.62
new diagnostic tables (1996-97), Feb.69
Super Crew (Ford), 2000 Light Truck Service Report, Jan.39
Supra (Toyota), steering gear service precaution (1996 newer), Dec.50
SUV (Saturn), 2002 model unveiled, Nov.68
Swapman.com
selling excess automotive parts, Jan.64
website address, Jan.64
Synthetic oils, pros and cons of, Feb.6, 86
Systems see specific systems

T

T100 (Toyota)
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
cylinder head service (1988-95), Apr.65
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
Tacoma (Toyota)
2.4-liter, lumpy idle (1995-97), Aug.59
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18
buzzing evap canister (1995-96), Nov.75
losing power and poor driveability at 3000 rpm (mid 90s), Feb.21
snow in HVAC box (1996-98), May.76
steering gear service precaution (1996 newer), Dec.50
upgraded automatic transmission (1996), May.72
Talon (Eagle)
2.0-liter, new transmission software (1996-97), Apr.59-60
intermittent cruise control (1995-99), Oct.28
PCM reflashing tips (1995-99), Dec.50
single-cylinder misfire (1995-96), Dec.48
squeaking or rubbing noise in rear (1995-98), Dec.56
TANA see Tire Association of North America (TANA)
Taurus (Ford)
3-liter
automatic transmission identification (1994-96), Mar.83
hesitation, delayed downshift (1996-97), Jun.63
3.4-liter, automatic transmission identification (1996), Mar.83
ABS noise (1998-99), Jun.74
automatic transmission identification (1986 on), Mar.83
blower motor squeak/chirp (1986-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Moog Automotive, improved non-greasable front stabilizer bar link (1986-95), Apr.54
no temperature control (1997-98), May.70
PCM reprogramming flash cable available (1996-99), Feb.72
popping noise in front end (1986-95), Jan.60
rear tire wear (1996-97), May.78
replacing the radiator, Aug.22
transmission DTCs stored in memory (1998), May.76
Taurus SHO (Ford), lack engine braking, rolling idle, spark knock (1998), Jun.66, 68
Tech-2-Tech, Honda Training & Information Systems diagnostics manual, Dec.65
Telephone numbers see under Contact information
Tempo (Ford)
2.3-liter, MIL on with no driveability problems (1988-94), Feb.68-69
3-liter, MIL on with no driveability problems (1992-94), Feb.68-69
blower motor squeak/chirp (1984-94), Aug.58, Nov.78
Tercel (Toyota)
steering gear service precaution (1996 newer), Dec.50
surging idle (1990-94), Jan.20, 22
Terradyne (GMC), concept vehicle unveiled at 2000 North American International Auto Show, Mar.77
Texas Natural Resource Conservation Commission (TNRCC), vehicle

scrappage program proposed, May.68
The Learning Channel (TLC), Junkyard Wars team search, Jun.75
Thermal mapping, with infrared thermometer, Mar.26
Thexton Manufacturing
Freeze Plug Starter and Driver Kit, Feb.74
IAC Motor Tester, Nov.81
THINK City
environmentally mobile division of Ford, Mar.78-79
website address, Mar.78
Throttle position sensors see under Sensors
Thunderbird (Ford)
3.8-liter, PCM reprogramming flash cable available (1996-97), Feb.72
4.6-liter, PCM reprogramming flash cable available (1994-97), Feb.72
black smoke, poor fuel economy (1988), Nov.20-22
blower motor squeak/chirp (1989-97), Aug.58, Nov.78
delayed upshift from reman 4R70W (1994-97), Aug.59
transmission DTCs stored in memory (1997), May.76
Tiburon (Hyundai)
revised TCMs (1997), Nov.75-76
timing chain noise (1997-98), Jun.68
Timing belts
inspection and replacement, Jul.39-40
OE Scheduled Maintenance Handbook Tech Tips, Feb.44-45
Vehicle Manufacturers' Recommended Timing Belt Replacement Intervals chart, Jul.41-48
Timing is Everything, Jul.39-48
Tire Association of North America (TANA), Global Automotive Aftermarket Symposium (GAAS), Jun.2
Tires and wheels
checking for excessive, unusual or uneven wear, Mar.70
diagnostics using infrared thermometers, Mar.26
Titan Tool Supply, optical inspection equipment catalog, Apr.66
TLC see The Learning Channel (TLC)
TNRCC see Texas Natural Resource Conservation Commission (TNRCC)
Tomco
4 Will Get You 1 brochure assortment, Nov.80
Chrysler
replacement aftermarket choke pinion gear, Jun.76
replacement MAP sensor (1987-90), Aug.66
Ford Pressure Feedback EGR Sensor, Jul.75
fuel & emissions parts catalog, Feb.73, Aug.62, Oct.31
fuel and emissions systems brochures offered, Dec.64
Mitsubishi, replacement aftermarket choke pinion gear, Jun.76
replacement O2 sensors, Oct.35-36
throttle air adjust space plate, Jan.65
wire and hose marking kit, Nov.81
Tools and equipment
see also Parts, accessories and supplies; Tools of the Trade; Top Twenty Tools
diagnostics with scan tools, Mar.22-26
dynamometers, Nov.42-47
ESP SystemOne, Nov.46
SPX Corp. Bear/Allen Emissary Series, Nov.46-47
Equipment and Tool Institute (ETI) Product Showcase, Nov.54-58, 60, 62, 64
graphing multimeters, Sep.42-47
infrared thermometers, Mar.22-26, Jun.26
Kent-Moore, ACR 2000 A/C Service Center, Apr.28, 30
lab scopes, May.51-54
Assessment quiz, May.55-56
scan tools, May.40-42, 44, 46-47
diagnosing fuel delivery problems, Feb.14, 16
waste oil heaters explored, Jan.48-49
Tools of the Trade
see also Parts, accessories and supplies; Tools and equipment; Top 20 Tools
Airsept, Service Compressor Suction Screen Kit, Aug.66
Amsoil, synthetic ATF+4 transmission fluid, Jul.75
Aremco Products, Pyro-Putty 2400 high temperature stainless steel paste, Oct.36
ATP, Re-Seal seal rejuvenator, Apr.68
Auto Meter, BVA-200 hand held tester, Oct.36
Automotive Electronics Services
DMM training video, Nov.81
Wire-Tap sharp wire piercer, Mar.91
Automotive Solutions, LeakFind 12 volt leak detection system, Apr.68
Bergwall Productions, ASE test prep guides, Jun.76
Brake Align, Runout Correction Plates, Jun.79
Brake Tru, RotorResurfacers on-car rotor resurfacers, Jul.75
Castrol, Syntec Power System fuel system cleaner, Jun.76
Challenger Lifts, Versymmetric above-ground lift, Jun.76
Coxreels, Poly-Pro hose reels, Dec.65
Crown Remanufacturing, remanufactured power steering pumps, Aug.66
Cuda Cleaning Systems, H20-2518V automatic parts washer, Oct.36
Cyclo Industries, Anti-Gel Diesel Fuel Treatment, Sep.78
E-Z Hook, XEL Test Connector, Jun.78-79
Eidos Corp., GlydeMaster ergonomically designed creeper, Oct.36
Exxon Mobil, Drive Clean Blend synthetic motor oil, Oct.36
Gates Rubber, updated Timing Belt Replacement Manual, Aug.66
GOJO, hand cleaner/brush combo, Sep.78
Gold Eagle, All-Season Water Remover, Jun.79
Gray Automotive, FSJ-40 floor jack, Jun.76
Hennessey Industries, Ammco Model 1450 Deluxe Brake Washer, Feb.74
Honeywell Consumer Products Group, Genetron 134aUV refrigerant/dye combo, Apr.68
Hotsy, Model 555 hot-water pressure washer, Jul.75
Hunter Engineering, OCL360 on-car brake lathe, Mar.91
Kastar Hand Tools, Torx ratcheting box wrench set, Jan.65
Ken-Tool, Bead-Eze tire lubricant, Mar.91
Kent-Moore, ACR 2000 A/C Service Center, Apr.68
Lenan
Lenair Recyclit Model SR80 XP solvent recycler, Jan.65
SR8ss waste solvent recycler, May.81
Leybold Inficom, TEK-Mate, refrigerant leak detector, Apr.68
Linder Technical Services, reman central port injection assemblies for GM, Jul.75
Matco Tools
combo fuel injector/EGR tester, Sep.80
Determinator Series ABS tester, Jun.76
Special Forces Air Ratchet, Oct.35
Mighty Auto Parts, Engine Guard II oil filters, Aug.66
M.M. Newman, Antex MLXS portable soldering iron, Sep.78
Mohawk Resources Ltd., HR-6 portable midrise lift, Dec.65
Motorvac Technologies, CoolantClean automated cooling system service machine, Oct.35
NAPA Hand Tools, new screwdriver set, Sep.79
NAPA/United, Moisture Alert Brake Fluid Test Strips, Sep.78-79
Orion Safety Products, first aid kits, Mar.91
OTC
Fuel Injection Service Kit, Jan.65
Model 1727 2-ton service jack, Jul.75
Smart Funnel, Sep.80
Under-Hoist Stand, Jun.78
Pennzoil-Quaker State, synthetic motor oil, Nov.81
Phoenix Systems, brake fluid test strips, Mar.91
Prism Enterprises
Mityvac Fluid Evacuator, May.81
Mityvac Heater & Evaporator Core Test Accessories Kit, Sep.79
Purolator Products, PureONE oil filters, Oct.36
Raybestos Brakes
Super Stop Severe Duty Rotors, Aug.66
Synthetic Moly Paste high-temperature brake lubricant, Mar.91
Rema Tip Top/North America, Rep Boy Tire Inspection & Repair Station, Oct.35
Rema Tip Top/North America, Angle-Head Tire Buffers, Nov.81
Robinair
CoolTech 134 compact a/c station, Sep.78
Engine Oil Service Solutions engine cleaning machine, May.81
Enviro-Charge Dual, a/c station, Jun.78
Rotor Clip, retaining ring pliers, Apr.68
Shenandoah Manufacturing, Horizon waster oil heaters, Dec.65
SK Hand Tool, metric impact socket set, Oct.35
Snap-on Diagnostics
1999 Fast-Track Domestic Transmission Troubleshooter Cartridge, Dec.65
secondary ignition tester for Vantage, May.81
Snap-on Tools
High Strength Sealed Ratchet Series, Oct.35
snap ring plier set, Nov.81
Soft Grip Ratcheting Screwdriver, Sep.78
Tech-2-Tech, Honda Training & Information Systems diagnostics manual, Dec.65
Thexton Manufacturing
Freeze Plug Starter and Driver Kit, Feb.74
IAC Motor Tester, Nov.81
Tomco
Chrysler
replacement aftermarket choke pinion gear, Jun.76
replacement MAP sensor (1987-90), Aug.66
Ford Pressure Feedback EGR Sensor, Jul.75
Mitsubishi, replacement aftermarket choke pinion gear, Jun.76
replacement O2 sensors, Oct.35-36
throttle air adjust space plate, Jan.65
wire and hose marking kit, Nov.81
Tracer Products, Tracerline BigEZ a/c dye injector and cartridge assembly, Aug.66
UView Ultraviolet Systems, Airlift Cooling System Air Purge, May.81
Valvoline, SynPower Nonchlorinated Brake Parts Cleaner, Jan.65
Vetronix, MTS 5100 Engine Analyzer, Feb.74
Wells Manufacturing, premium spark plug wires, Feb.74
Top 20 Tools
see also Tools and equipment; Tools of the Trade
Airsept, Service Compressor Suction Screen Kit, Sep.30
Automotive Service Training, Silver Bullets Diagnostics Tips Manual, Sep.27
Blue Streak Electronics, BDM Diagnostic Monitor, Sep.27
Chart Industries, Twinn-Lift Tech-Centre, Sep.30
DATEC, Coil On Plug-II Ignition Tester, Sep.40
EASE Diagnostics, Wireless Vehicle Interface, Sep.37-38
Ferret Instruments, Ferret 55 EngineLink Diagnostic Analyzer, Sep.34-35
Hunter Engineering, Virtual View Alignment Software, Sep.32, 34
Kent-Moore, ACR 2000 A/C Service Center, Sep.36-37
Lisle, Spill-Free Coolant Funnel, Sep.31
Mac Tools, Flex Head Indexable Ratchet, Sep.32
Mastercool, A/C Valve Core Remover/Reinstaller Kit, Sep.30-31
Matco Tools, Special Forces 3/8-inch Air Ratchet, Sep.35-36
OTC, Genisys Information System, Sep.32
Pro-Cut International, Discus Rotor Measuring System, Sep.28
Run-Rite, Intake Snake, Sep.27-28
Snap-on Diagnostics, kV Secondary Ignition Module, Sep.28, 30
Snap-on Tools, Latch-on Ratcheting Box Wrenches, Sep.36
UView Ultraviolet Systems, Airlift Cooling System Air Purge, Sep.38
Vetronix, MTS 5100 Engine Analyzer, Sep.38-39
Topaz (Mercury)
2.3-liter, MIL on with no driveability problems (1988-94), Feb.68-69
3-liter, MIL on with no driveability problems (1992-94), Feb.68-69
blower motor squeak/chirp (1984-94), Aug.58, Nov.78
Town & Country (Chrysler)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
2001 model unveiled at 2000 North American International Auto Show, Mar.80-81
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
Town Car (Lincoln)
4.6-liter, no crank (1991-94), Mar.88
ABS noise (1998-99), Jun.74
delayed upshift from reman 4R70W, DTC P0782 (1995-99), Jun.68-69, Aug.59, Dec.50
fuel pump service tip (1998), Sep.70, 72
hesitation with TCS active (1998), Dec.48
MIL on, no symptoms (1997), Apr.63-64
no temperature control (1997), May.70
overheating/diminished heater output (1990), Sep.12, 14-15
PCM reprogramming flash cable available (1995-99), Feb.72
poor a/c performance, thumping noise (1998), Dec.57
rear brake squeal/moan (1995-96), Sep.75-76
transmission DTCs stored in memory (1998), May.76
Toyota
see also specific models
2000 Light Truck Service Report, Jan.36-37
binding driveshaft slip-joints, Mar.21
MAP sensor testing, Mar.20-21
O2 sensor flange gasket leakage, Mar.21
surging idle, Jan.20, 22
troubleshooting throttle openers, fast-idle valves, throttle position sensors (TPS), Jan.20, 22
Toyota Motor Sales, USA, Internet B2B e-commerce alliance formed with i2 Technologies, Apr.50
Toyota Racing Development
contact information, Jul.74
parts, performance data, reference guides, application charts catalog, Jul.74
Tracer (Mercury)
1.9-liter, PCM reprogramming flash cable available (1996), Feb.72
2-liter, PCM reprogramming flash cable available (1997-99), Feb.72
blower motor squeak/chirp (1991-97), Aug.58, Nov.78
brake noise (1997-99), Jul.60, 68
front brake knocking noise (1991-96), Oct.28
Tracer Products
Tracerline BigEZ a/c dye injector and

2000 Motor Magazine Index

cartridge assembly, Aug.66
Tracerline leak detection products brochure, Dec.64
Tracker (Geo)
1.6-liter, emissions inspection failure (1995), Apr.6, 10-11
lack of power in snowstorms (1996-98), Oct.27
Traction control systems see under Antilock brake systems (ABS)
Trade Secrets
6000 (Pontiac), misfire with a/c or heater on (1987), Aug.12-13
avoiding the quick fix for emission failures, Apr.6, 10-11
building trust in new customers, Nov.10, 12-13
Century (Buick), 2.5-liter, intermittent no start, Jan.12, 15-16
checking for fire safety in your shop, Jun.10, 13, 15
diagnostics-test, don't guess, Jul.10, 12-13
extended warranty coverage precaution, Dec.12, 14-15
filling lulls with "elective" jobs, Mar.10, 12-13
interaction with co-workers, Mar.10, 12-13
Intrepid (Dodge), subframe replacement (2000), May.10, 12
Mustang (Ford), 5-liter, won't shift into any gear with motor running, Jul.10, 12-13
Neon (Dodge/Plymouth), 2-liter, shaking and check engine light on (1997), Feb.10, 11-12
not letting customers push you into not doing the job right, Sep.12, 14-15
not taking insurance coverage for granted, Jun.10, 13, 15
Park Avenue (Buick), failed emissions test (1994), Nov.12-13
pride for a job well done, Feb.10, 11-12
receives 10th International Automotive Media Conference (IAMC) Gold Medallion award, Dec.62
taking time to talk to new customers, Jan.12, 15-16
Town Car (Lincoln), overheating/diminished heater output (1990), Sep.12, 14-15
Tracker (Geo), 1.6-liter, emissions inspection failure (1995), Apr.6, 10-11
treating customers as you would like to be treated, Oct.10, 12-13
understanding customers' motivations, Aug.10, 12-13
using curiosity to solve "impossible" problems, May.10, 12
writing work orders, Jan.12, 15-16
Training
see also Education
keeping up with a/c regulations and certification, Mar.4
National Institute for Automotive Service Excellence (ASE), test prep guides, Jun.76
Uniform Inspection & Communication Guidelines (UICG), Internet-based training program, Sep.77
Trans Am (Pontiac), engine miss, poor driveability (1993-97), Jun.63
Trans Sport (Pontiac)
3.4-liter, hard-start/no-start (1996), Jan.62
3100/3400/3800, hard-start/no-start (1996), Jan.62
intermittent Neutral on the highway (1995-97), Sep.73
Transmission systems
see also Automatic transmission systems
Avenger (Dodge) new transmission software, Apr.59-60
Chrysler's new 45RFE transmission explained, Jun.35-38
OE Scheduled Maintenance Handbook Tech Tips, manual gearboxes, differentials & transfer cases, Feb.36
Tribute (Mazda), 2001 Import Tech Roundup, Dec.33
Trooper (Isuzu)
3.2-liter
updated timing belt adjustment interval, valve adjustment (1998), Jun.69-70
valvetrain tick (1997 and earlier), Dec.57
Trouble Shooter
Accord (Honda), 2.2-liter, timing belt/water pump replacement precaution, Dec.6, 8
Astro (Chevrolet), ABS light on/spongy pedal (1994), Nov.4, 6
Corvette (Chevrolet)
higher-than-normal temperature gauge reading (1994), Jun.4, 6
non-linear analog temperature gauge (1990-96), Aug.4, 6
G20 (Chevrolet)
ongoing screeching brake problem (1996), May.4, 7
screeching noise when braking (1996), Jan.6, 11
Grand Cherokee (Jeep)
5.2-liter, detonation complaints (1992-2000), Oct.6, 8
5.9-liter, detonation complaints (1992-2000), Oct.6, 8
isolating brake lockup problem, Mar.6-7
K2500 (GMC), rear wheel lockup and slight pull (1990), Mar.6-7
Maxima (Nissan), no heat after cooling system flush (late 80s-early 90s), Feb.4-5
Mobile 1, pros and cons of synthetic oil, Feb.6, 86
Park Avenue (Buick)
3.8-liter
excessive oil consumption, tests ok, Sep.6, 8
revised dipstick tube and dipstick, Sep.6, 8
Truck (Chrysler)
3.9-liter, detonation complaints (1992-2000), Oct.6, 8
5.2-liter, detonation complaints (1992-2000), Oct.6, 8
5.9-liter, detonation complaints (1992-2000), Oct.6, 8
Truck (General Motors), breaking loose the ball joint/control arm rivets, Jul.4
using your shop's water heater to test radiator core temperature, Aug.6
Truck (Chrysler)
3.9-liter, detonation complaints (1992-2000), Oct.6, 8
5.2-liter, detonation complaints (1992-2000), Oct.6, 8
no charge condition (1996-98), Nov.75
Truck (General Motors), breaking loose the ball joint/control arm rivets, Jul.4
Truck (Toyota)
cylinder head service (1988-95), Apr.65
misleading sensor signals (late 80s-early 90s), Feb.18, 21
surging idle (1988-94), Jan.20, 22
Tundra (Toyota)
2000 Light Truck Service Report, Jan.36-37
3.4-liter, timing belt replacement tips (1995 on), Dec.16, 18

U

UICSs see Uniform Inspection and Communication Standards (UICSs)
ULEV see Ultra Low Emission Vehicle (ULEV)
Ultra Low Emission Vehicle (ULEV), Insight (Honda) introduced, Jan.57
Uniform Inspection & Communication Guidelines (UICG), Internet-based training program, Sep.77
Uniform Inspection and Communication Standards (UICSs)
fighting negative image of automotive aftermarket industry, Jun.42
media reaction to, Aug.47
University of the Aftermarket
Global Automotive Aftermarket Symposium (GAAS), Jun.2
joins Northwood University, Dec.64
UOMA see Used Oil Management Association (UOMA)
U.S. Public Interest Research Group, protest dropping Florida emissions tests, Jul.63, 65
U.S. Senate Commerce Committee, targets defective vehicle parts, Nov.71
Used oil see waste oil
Used Oil Management Association (UOMA)
information on waste oil heaters available, Jan.49
website address, Jan.49
Used Oil Management Standards, Environmental Protection Agency (EPA), used oil recycling exemptions, Jan.49
UView Ultraviolet Systems, Airlift Cooling System Air Purge, May.81, Aug.26-27, Sep.38

V

V70 Cross Country (Volvo), 2001 Import Tech Roundup, Dec.33-34
V70 (Volvo), new O2 sensor wiring (1996-98), Apr.60
V90 (Volvo), revised power steering parts (1997), Nov.78
Valvoline, SynPower Nonchlorinated Brake Parts Cleaner, Jan.65
Varsity (Jeep), concept vehicle unveiled at 2000 North American International Auto Show, Mar.75
Vehicle speed sensors (VSS) see under Sensors
Ventura (Chevrolet), intermittent Neutral on the highway (1997), Sep.73
Vetronix, MTS 5100 Engine Analyzer, Feb.74, Sep.38-39
Villager (Mercury)
blower motor squeak/chirp (1993-97), Aug.58, Nov.78
rear blower doesn't work (1993), Apr.28
temperature display oddity (1996-98), Apr.56
Viper (Dodge), PCM reflashing tips (1995-99), Dec.50
Viper GTS/R (Dodge), concept vehicle unveiled at 2000 North American International Auto Show, Mar.76
Vision (Eagle)
a/c leak (1995-97), Nov.79
3.3-liter, hesitation, rough idle, DTCs stored (1995-96), Apr.55
3.5-liter
fuel system recall (1993-97), Mar.83
hesitation, rough idle, DTCs stored (1995-96), Apr.55
intermittent cruise control (1993-97), Oct.28
PCM reflashing tips (1995-99), Dec.50
refrigerant loss (1995-97), May.76-77
seized blower motor (1993-97), Jun.60
Visteon Automotive Systems
ClimatePro Air Conditioning Components Applications Catalog and Illustrated Guide, Jul.74
ClimatePro Heat Transfer Components Applications Catalog and Illustrated Guide, Jul.74
contact information, Jul.74
new alternator design, May.22, 24-25
scholarship established, May.79
Volvo
see also specific models
Volvo Tech Tips flyers, Oct.30
Voyager (Plymouth)
3-liter, harsh shifting (1990-95), Feb.69
3.3-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
3.8-liter, serpentine belt pops off idler (1996-99), Jul.66, 68
2001 model unveiled at 2000 North American International Auto Show, Mar.80-81
burnt ATF (1996-97), Dec.52
cam sensor oil leak (1996-99), Jan.60-61
false body computer DTC (1998-99), Jul.70
intermittent cruise control (1989-99), Oct.28
new transmission software (1996-97), Apr.58-59
PCM reflashing tips (1995-99), Dec.50
VSS see Vehicle Speed Sensors (VSS) under Sensors

W

Wal-Mart, Tools for Schools program, Oct.30
Waste oil, tips for proper storage and disposal, Jan.44-46, 48-49
Waste Oil at Your Disposal, Jan.44-46, 48-49
Waste oil heaters, information and regulations, Jan.48-49
Waterloo Industries, tool storage products catalog, Dec.64
Wells Manufacturing, premium spark plug wires, Feb.74
W.G. Nichols, Inc., MOTOR Magazine lawsuit, Jan.2, 4
Wheel alignment, using infrared thermometers, Mar.26
Windstar (Ford)
ABS noise (1998-99), Jun.74
automatic transmission identification (1995 on), Mar.83
blower motor squeak/chirp (1995-97), Aug.58, Nov.78
fuel pump service tip (1998), Sep.70, 72
PCM reprogramming flash cable available (1995-99), Feb.72
Wiper/washer systems, OE Scheduled Maintenance Handbook Tech Tips, Feb.51
WIX Filtration Products
Future Farmers of America contribution, Jan.64
NASCAR and NHRA racing contract extensions, Apr.66
Wrangler (Jeep)
false MIL with various DTCs (1997), Nov.79
no charge condition (1997-98), Nov.75
PCM reflashing tips (1995-99), Dec.50
slow fuel fill-up (prior to 11/22/96), Jan.60
sluggish acceleration, false MIL (1998-99), May.73-74
transfer case shifter noise (1997-99), Mar.84-85
Wrenchead.com, Inc., Wrenchead Pro turnkey business-to-business system, Sep.77

X

X5 (BMW), VIN code changes, Jan.57
XJ8 (Jaguar)
intermittent dash lights with false warnings (1998), Dec.52
transmission recall/replacement (1999), Jun.62
XJ12 (Jaguar), waterlogged PCM (1995), May.77
XJS (Jaguar), stuck throttle on cold engine (1995-96), May.71-72
XK8 (Jaguar)
higher idle speeds (1997 newer), Jun.64-65
intermittent dash lights with false warnings (1998), Dec.52
transmission recall/replacement (1999), Jun.62
XM Satellite Radio, Honda/OnStar/XM Satellite Radio team up to offer mobile communication services, Jul.62-63
XRJ (Jaguar), waterlogged PCM (1995), May.77
Xterra (Nissan), 2000 Light Truck Service Report, Jan.41
XVL (Infiniti), concept vehicle unveiled at 2000 North American International Auto Show, Mar.77

Y

Yahoo! Autos, teams up with Ford's Owner Connection, Mar.75
Yukon (GMC), 2000 Light Truck Service Report, Jan.36-37

Z

Z3 (BMW)
2.8-liter
proper thermostat replacement (1998 newer), Dec.50
valve timing mechanism jams (1997), Apr.57
VIN code changes, Jan.57